

Heritage Consulting Group Photo

Description: S elevation looking NW

Date: November, 1999

Negative location:

Heritage Consulting Group 123 NW Second Avenue #200 Portland, Oregon 97209 (503) 228-0271 Photo _____ of ____



Heritage Consulting Group Photo

Description: S and W elevations, looking NE

Date: November, 1999

Negative location:

Photo Z of



Heritage Consulting Group Photo

Description: W and N elevations looking SE

Date: November, 1999

Negative location:

Photo 3 of 14



Heritage Consulting Group Photo

Description: Looking SE at Brew House, Malt and Hop House, Ice and Power Plant, chimney stack

Date: November, 1999

Negative location:

Photo



Heritage Consulting Group Photo

Description: N elevation looking S

Date: November, 1999

Negative location:

Photo 5 of



Heritage Consulting Group Photo

Description: S and E elevation looking NW

Date: November, 1999

Negative location:

Photo 10 of 14



Heritage Consulting Group Photo

Description: Detail W elevation

Date: November, 1999

Negative location:

Photo 7 of 4



Heritage Consulting Group Photo

Description: Detail Malt and Hops House S elevation

Date: November, 1999

Negative location:

Photo 🔏 of



Heritage Consulting Group Photo

Description: Detail W elevation

Date: November, 1999

Negative location:

Photo 9 of 14



Heritage Consulting Group Photo

Description: Detail W elevation

Date: November, 1999

Negative location:

Photo 10 of 14



Heritage Consulting Group Photo

Description: Interior detail door located between Malt and Hops House and Brew House

Date: November, 1999

Negative location:

Heritage Consulting Group 123 NW Second Avenue #200 Portland, Oregon 97209 (503) 228-0271

Photo 1 of



Heritage Consulting Group Photo

Description: Interior detail of mezzanine railing

Date: November, 1999


Negative location:

Photo 2 of 4



Weinhard Brewery Complex 1131-1133 West Burnside Portland, Multnomah County, Oregon Heritage Consulting Group Photo Description: Interior stairwell Date: November, 1999 Negative location:

Photo 3 of 14



Heritage Consulting Group Photo

Description: Interior Brew House

Date: November, 1999

Negative location:

Heritage Consulting Group 123 NW Second Avenue #200 Portland, Oregon 97209 (503) 228-0271

Photo 4 of 14