



Kraft-Brandes-Culbertson home

2525 No. Baker Dr.

Canby, Ore.

Martin & Kurt Schrader

1925-1928

West side
view of the home

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

1 of 22

Historic view, 1925-1928. West
elevations of pumphouse and farmhouse
from upper pasture. Camera facing
east.

Culbertson Family Collection
Negative: Dr. Kurt Schrader
2525 No. Baker Drive
Canby, OR 97013



Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

2 of 22

Historic view, 1925-1928. West
elevations of pumphouse and farmhouse
from fenced area of barnyard.
Camera facing east.

Culbertson Family Collection
Negative: Dr. Kurt Schrader
2525 No. Baker Drive
Canby, OR 97013

*Kraft-Brandes-Culbertson home
2525 No. Baker Dr.
Canby, Ore.*

Martha & Kurt Schrader

1925-1928

View of the West side of house & pumphouse



Kraft Brandes - Culbertson Home
2525 No. Baker Drive
Canby, Ore.

Martha + Kurt Schrader

East side of House 1925-1928

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

3 of 22

Historic view, 1925-1928. East
elevation of farmhouse. Camera
facing west.

Culbertson Family Collection
Negative: Dr. Kurt Schrader
2525 No. Baker Drive
Canby, OR 97013



Kraft - Brandeis - Culbertson Home
2525 No. Baker Drive
Canby, Ore.

Martha & Kurt Schrader

1925-1928

Northeast corner of the home

Kraft-Brandeis-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

4 of 22

Historic view, 1925-1928. East
elevation and north end elevation of
farmhouse. Pumphouse is to right.

Camera facing west.

Culbertson Family Collection
Negative: Dr. Kurt Schrader
2525 No. Baker Drive
Canby, OR 97013



Kraft-Brandes Culbertson Home

2525 No. Baker Dr.

Canby, Ore.

Martha + Kurt Schrader

1925-1928


Northeast Corner of the home

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

5 of 22

Historic view, 1925-1928. Northeast
corner of farmhouse. Camera facing
southwesterly.

Culbertson Family Collection
Negative: Dr. Kurt Schrader
2525 No. Baker Drive
Canby, OR 97013



Kraft - Brandeis - Culbertson name

2525 No. Baker Dr.

Canby, Ore.

Martha & Kurt Schrader

1925-1928

South View of Barn and Machine shed

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

6 of 22

Historic view, 1925-1928. Machine
shed (no longer standing), siloes (no
longer standing) and barn, (west and
south elevations). Camera facing

northeasterly.

Culbertson Family Collection
Negative: Dr. Kurt Schrader
2525 No. Baker Drive
Canby, OR 97013



Kraft-Brandes - Culbertson home

2525 No. Baker Dr.

Canby, Ore.

Martha & Kurt Schrader

1925-1928

Lower 40 Acres

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

7 of 22

Historic view, 1925-1928. Looking north from wooded ridge top which marks northerly boundary of nominated area over lower 40 acres of farm, not

included in nominated area. Location of Willamette River in far ground is marked by break of trees, rise of hills.

Culbertson Family Collection
Negative: Dr. Kurt Schrader
2525 No. Baker Drive
Canby, OR 97013



Kraft - Brandeis - Culbertson Farm
2525 No. Baker Drive.

Canby, Ore.

Martha & Kurt Schrader

1925-1928

Haying on the lower 40 Acres

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

8 of 22
Historic view, 1925-1928. Haying
on the lower 40 acres.

Culbertson Family Collection
Negative: Dr. Kurt Schrader
2525 No. Baker Drive
Canby, OR 97013



Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

9 of 22
Haystack on the lower 40 acres.

Culbertson Family Collection
Negative: Dr. Kurt Schrader
2525 No. Baker Drive
Canby, OR 97013

Kraft - Brandeis - Culbertson Name

2525 No. Baker Dr.

Canby, Ore.

Martha & Kurt Schrader

1925-1928

Hay from Three Rivers Farm



Three Rivers Farm -
2525 N. Baker Dr.
Canby, Ore. Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

10 of 22
West elevation of farmhouse.

de of house

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

March 1982

Photo by:
Martha + Kurt Schrader



Three Rivers Farm

2525 N. Baker Dr.

Canby, Ore.

Clackamas County

Kraft-Brandes-Culbertson Farmstead

"Three Rivers Farm"

2525 No. Baker Drive

Canby vicinity, Clackamas County, Oregon

11 of 22

Detail of central portion, west
elevation, farmhouse.

Kurt Schrader Photo, March, 1982

2525 No. Baker Drive

Canby, Oregon 97013

Photo by:

Martha + Kurt Schrader

March 1982



Three Rivers Farm
2525 N Baker Dr.
Canby, Ore.

Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

12 of 22

Sun room, northwest corner of
farmhouse.

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

Photo by:
Martha & Kurt Schrader

March 1982



Three Rivers Farm
2525 N Baker-Dr.
Canby, Ore.

Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

of house

13 of 22
Southwest corner of farmhouse, showing
balcony atop veranda on south end.

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

Photo by:
Martha + Kurt Schrader

March 1982



Three Rivers Farm
2525 N. Baker Dr.
Canby, Ore Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

14 of 22
South end elevation of farmhouse showing
double veranda.

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

March 1982

Photo by:
Martha Kurt Schrader



Three Rivers Farm
2525 N. Baker Dr.
Canby, Ore. & Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

15 of 22
Detail of upper story, south end
elevation of farmhouse.

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

Photo by:
Martha + Kurt Schrader

March 1982



Three Rivers Farm
2525 N. Baker Dr.
Canby, Ore.

Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

16 of 22

East elevation of farmhouse. East end
of barn is visible in background.

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

Photo by:

Martha & Kurt Schrader

March 1982



Three Rivers Farm
2525 N. Baker Dr.
Canby, Ore.

Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

17 of 22
Northeast corner of farmhouse and
detached pumphouse. Barn is in
background.

of house

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

*Photo by:
Martha + Kurt Schrader*

March 1982



Three Rivers Farm
2525 N Baker Dr.
Canby, Ore. Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

18 of 22
North end elevation of farmhouse.

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

Photo by
Martha & Kurt Schrader

March 1982



Three Rivers Farm
2525 N. Baker Dr.
Canby, Ore.

Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

19 of 22

Detail of upper story, north end
elevation of farmhouse.

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

Photo by:

Martha + Kurt Schrader

March 1982



Three Rivers Farm
2525 N. Baker Dr.
Canby, Ore.

Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

20 of 22
East end elevation of barn showing
hooded hayfork lift, original board
and batten siding.

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

March 1982

Photo by:
Mortlar Kurt Schrader



Three Rivers Farm
2525 N Baker Dr.
Canby, Ore.

Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

21 of 22
South elevation of barn showing early
lean-to addition.

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

March 1982

Photo by:
Martha + Kurt Schrader



Three Rivers Farm
2525 N. Baker Dr.
Canby, Ore.

Clackamas County

Kraft-Brandes-Culbertson Farmstead
"Three Rivers Farm"
2525 No. Baker Drive
Canby vicinity, Clackamas County, Oregon

22 of 22
West end and south elevation of barn
showing roof ridge ventilator.

Kurt Schrader Photo, March, 1982
2525 No. Baker Drive
Canby, Oregon 97013

March 1982

Photo by:

Martha & Kurt Schrader