



C. & M. Lohr House

Estelline, SD

Carolyn Torma

1981

Historical Preservation Center  
front, :south: facade

Photo 1



C. & M. Lohr House

Estelline, SD

Carolyn Torma

1981

Historical Preservation Center

rear, north facade

Photo 2



C. & M. Lohr House

Estelline, SD

Carolyn Torma

1981

Historical Preservation Center  
side, east facade

Photo 3



C. & M. Lohr House

Estelline, SD

Carolyn Torma

1981

Historical Preservation Center  
side, west facade

Photo 4



C. & M. Lohr House

Estelline, SD

Carolyn Torma

1981

Historical Preservation Center  
barn & chicken coop/tool room

Photo 5



C. & M. Lohr House

Estelline, SD

Carolyn Torma

1981

Historical Preservation Center

stove vent, 2nd floor, interior detail

Photo 6



C. & M. Lohr House

Estelline, SD

Carolyn Torma

1981

Historical Preservation Center

detail, front, south window

Photo 7



C. & M. Lohr House

Estelline, SD

Carolyn Torma

1981

Historical Preservation Center

wallpaper, bathroom

Photo 8



C. & M. Lohr House

Estelline, SD

Carolyn Torma

1981

Historical Preservation Center

wooden toilet

Photo 9



C. & M. Lohr House  
Estelline, SD  
Carolyn Torma  
1981

Historical Preservation Center  
kitchen cupboard  
Photo 10