

Series A, Historic views, 1 of 17 Angelus photo Ground story front prior to remodeling of 1929-1920. Negative no. 66907



Series A, Historic views, 2 of 17 Facade upon completion of remodeling, 1930. Negative no. 66912



Series A, Historic views, 3 of 17 Street front display window south of entrance, 1930. Negative no. 66910



Series A, Historic views, 4 of 17 Display window, Broadway Street entrance, 1930.
Negative no. 66922



Display window, entrance vestibule, 1930. Negative no. 66921

Series A, Historic views, 5 of 17



Series A, Historic views, 6 of 17

First floor interior from entrance, 1930, looking west. Hosiery and lingerie.
Negative no. 66920

Oregon Historical Society

1230 SW Park Avenue Portland, OR 97205



Series A, Historic views, 7 of 17

First floor interior, 1930, looking east toward entrance. Elevators and stairway to upper floors on right.

Gloves and umbrellas. Negative no. 66915



Series A, Historic views, 8 lf 17 First floor interior, 1930, looking east toward street entrance from Chumley Sport Shop. Hosiery and

lingerie. Negative no. 66919



Series A, Historic views, 9 of 17

First floor interior, 1930, looking north from stairway. Negative no. 66916

Oregon Historical Society 1230 SW Park Avenue

Portland, OR 97205



Series A, Historic views, 10 of 17 First floor interior, 1930, Chumley Sport Shop, rear of first floor. Negative no. 66911



Series A, Historic views, 11 of 17 Second floor interior, 1930, looking southwesterly at elevator. Negative no. 66908



Series A, Historic views, 12 of 17

Second floor interior, 1930, looking northwesterly. Foundation garments.

Oregon Historical Society 1230 SW Park Avenue Portland, OR 97205

Negative no. 66917



Series A, Historic views, 13 of 17 Second floor interior, 1930, looking east. Millinery department. Negative no. 66918

Oregon Historical Society 1230 SW Park Avenue

Portland, OR 97205



Berg, Charles F., Building 615 SW Broadway Portland, Multnomah County, Oregon Series A, Historic views, 14 of 17 Third floor interior, 1930, looking east. Chumley Dress Shop. Negative no. 66909



Series A, Historic views, 15 of 17 Third floor interior, 1930, east end, looking south. Fashion salong. Negative no. 66906



Series A, Historic views, 16 of 17 Third floor interior, 1930, west end, looking south. Coat salon. Negative no. 66905.

Oregon Historical Society 1230 SW Park Avenue

Portland, OR 97205



Series A, Historic views, 17 of 17 Remodeled facade, ca. 1930, looking west from Broadway.

McMath-Doyle Collection, Lot 72



Heritage Investment photo, 1983 1303 Terminal Sales Building Portland, OR 97205

l or 7 Series B, current views Broadway Street facade (east elevation)



Heritage Investment photo, 1983 1303 Terminal Sales Building Portland, OR 97205

2 of 7 Series B, current views Broadway Street facade (east elevation)



1303 Terminal Sales Building Portland, OR 97205

Heritage Investment photo, 1983

3 of 7 Series B, current views Close view of main entrance as remodeled in 1975



Heritage Investment photo, 1983 1303 Terminal Sales Building Portland, OR 97205

4 of 7
Series B, current views
Close view of main entrance as remodeled in 1975. Bronze letters of building title are original.



Portland, OR 97205

5 of 7
Series B, current views
Detail of upper facade, showing

polychrome terra cotta spandrels.

Heritage Investment photo, 1983



Heritage Investment photo, 1983 1303 Terminal Sales Building Portland, OR 97205

6 of 7
Series B, current views
Detail of central terra cotta spandrel
panels with Art Deco ornament in
basrelief.



Heritage Investment photo, 1983 1303 Terminal Sales Building Portland, OR 97205

7 of 7
Series B, current views
Detail of parapet showing zig zag
repeating ornament. Streamline-Moderne

pilasters of black terra cotta are

highlighted with gold.