



Veter HERMAN House 1890
5830 SE Taylor
Portland Multnomah County Oregon 97215

Photographer Patrick Smith
November 1991

Location of Negative 5830 SE Taylor
Portland, Oregon 97215

1 of 39

Exterior northern elevation from S.E TAYLOR



VETTER, HERMAN House
5830 SE Taylor
Portland, Multnomah County Oregon 97215

Photographer Patrick Smith
November 1991

Location of negative: 5830 SE Taylor

2 of 34
EXTERIOR: WESTERN ELEVATION



Vetter, Herman House 1891
5830 SE Taylor
Portland, Multnomah County Oregon

Photographer Patrick Smith
NOVEMBER 1971

Location of negative 5830 SE Taylor
Portland Oregon

3 of 34
Exterior Southern Elevation



Vetter, HERMAN House 1890
5830 S.E. Taylor
Portland, Multnomah County, Oregon 97215

Photographer Patrick Smith
November 1991

Location of negative: 5830 SE Taylor
Portland Oregon 97215

4 of 34
Exterior EASTERN ELEVATION



VETTER, HERMAN House (1890)
5830 S.E. Taylor
Portland, Multnomah County
Oregon 97215

Photographer: Patrick Smith
NOVEMBER 1991

Location of negative 5830 SE TAYLOR
Portland Oregon
97215

5 of 34
EXTERIOR

Wraparound Porch detail EASTERN E



VETER HERMAN House 1890
5830 SE Taylor Street
Portland, Multnomah County Oregon

Photographer Patrick Smith
NOVEMBER 1997

Location of negative 5830 SE Taylor
Portland Oregon
97215

6 of 34
Detail North East corner wraparound porch



Vetter, HERMAN House 1890
5830 SE Taylor
Portland Multnomah County Oregon 97215

Photographer Patrick Smith
November 1991

Location of negative 5830 SE Taylor
Portland Oregon 97215

7 of 34
Detail of wraparound porch - View towards Taylor



Veter, Herman House 1890

5830 SE Taylor

Portland Multnomah County, Oregon 97215

Photographer Patrick Smith
November 1991

Location of negative 5830 SE Taylor
Portland Oregon 97215

8 of 34
Foundation / View taken from EASTERN E



VETTER, HERMAN House 1890
5830 S.E. TAYLOR
Portland, Multnomah County
Oregon 97215

Photographer P. Smith
NOVEMBER 1991

Location of negative, 5830 SE TAYLOR
Portland Ore
97215

4 of 34
Detail Front Eable Northern Elevation



Vetter, Herman House 1890

5830 SE Taylor

Portland, Multnomah County, Oregon 97215

Photographer Patrick Smith

November 1991

Location of negative

5830 S.E. Taylor
Portland Oregon 97215

10 of 34

detail of Sunburst Pattern / front Gable northern
elevation



VETER, HERMAN House 1890

5830 S.E. Taylor

Portland, Multnomah County, Oregon 97215

Photographer Patrick Smith
NOVEMBER 1991

Location of negative 5830 S.E. Taylor
Portland, Oregon 97215

11 of 34

Detail of second story arched window in
tower northeaster corner



Vetter, Herman House 1891
5830 SE Taylor
Portland, Multnomah County Oregon 97215

Photographer: Patrick Smith
NOVEMBER 1991

Location of negative 5830 SE TAYLOR
Portland Oregon
97215

12 of 34
Entrance to Front Parlor from Foyer



VETER GERMAN HOUSE 1890
5830 SE TAYLOR
Portland, Multnomah County Oregon 97215

Photographer Patrick Smith
NOVEMBER 1991

Location of negative 5830 SE Taylor
Portland Oregon
97215

13 of 34
Detail of wooden columns separating
parlour from foyer



Vetter, Herman House 1896

5830 SE Taylor,
Portland, Multnomah County, Oregon 97215

Photographer, Patrick Smith
November, 1991

Location of negative 5830 SE Taylor
Portland Oregon
97215

14 of 34
Front Parlour



Veteran's man house 1890
5830 SE Taylor
Portland, Multnomah County Oregon 97215

Photographer Patrick Smith
November 1991

Location of Negative: 5830 SE Taylor
Portland, Oregon
97215

15 of 34
Pocket doors separating Parlour 5



Vette, Herman House 1890
5830 SE Taylor
Portland Multnomah County, Oregon 97215

Photographer Patrick Smith
November 1991

Location of negative 5830 SE Taylor
Portland, Oregon

16 of 34
second parlour / sitting rooms



Vette, Herman House 1890
5830 SE Taylor
Portland Multnomah County, Oregon 97215

Photographer Patrick Smith
November 1991

Location of negative 5830 SE Taylor
Portland, Oregon 97215

17 of 34
second part of fireplace



Vetter, Herman House 1890

5830 SE Taylor

Patland, Multnomah County, Oregon 97215

Photographer: Patrick Smith
November 1991

Location of negative: 5830 SE Taylor
Patland, Oregon
97218

18 of 34

Detail of interior doors leading into library



Vetter Herman House 1890
5830 SE Taylor
Portland, Multnomah County, Oregon 97215

Photographer Pat Smith
November 1991

Location of Negative 85830 SE Taylor
Portland, Oregon 97215
19 of 34
view of Parlours facing North



Veter Herman house 1890
5830 SE Taylor
Portland Multnomah County, Oregon 97215

Photographer Patrick Smith
November 1991

Location of negative: 5830 SE TAYLOR
20 of 34 Portland, Oregon 97215
Detail of kitchen and second parlor door



VETER HERMAN House 1890
5830 SE TAYLOR
Portland Multnomah County, Oregon 97215

Photographer: Patrick Smith
November 1991

Location of negative: 5830 SE Taylor
Portland Oregon 97215

21 of 34
pantry



Vetter, Herman House 1890
5830 SE TAYLOR
Portland Multnomah County, Oregon 97215

Photographer, Patrick Smith
November 1991

Location of negative: 5830 SE TAYLOR
Portland, Oregon
97215

22 of 34
Dining Room/ Pass. through window + pantries



Velten, Herman House 1890

5830 SE Taylor

Portland, Multnomah County Oregon 97215

Photographer: Patrick Smith
November 1991

Location of negative 5830 SE Taylor
Portland, Oregon 97215

23 of 34
Library



Velter Herman House 1890
5830 SE Taylor
Portland Multnomah County, Oregon 97215

Photographer Patrick Smith
November, 1991

Location of Negative 5830 SE Taylor
Portland, Oregon 97215
24 of 34
first floor bathroom



Vetter, Herman House (1890)
5830 SE Taylor
Portland, Multnomah County, Oregon 97215

Photographer: Patrick Smith
November 1991

Location of negative: 5830 SE Taylor
Portland Oregon 97215

25 of 34
Stairwell on first floor



Vetter, HERMAN House 1890
5830 SE TAYLOR
Portland, Multnomah County Oregon 97215

Photographers Patrick Smith
November 1901

Location of negative 5830 SE TAYLOR
Portland Oregon 97215

26 of 34
Stairwell case leading to second floor



Velten, Herman House 1890

5830 SE Taylor

Portland Multnomah County Oregon 97215

Photographer: Patrick Smith
NOVEMBER 1991

Location of negative: 5830 SE Taylor
Portland Oregon 97215

27 of 34
Second floor trunk room



Vetter Herman House 1890
5830 SE TAYLOR
Portland Multnomah County, Oregon 97215

Photographer: Patrick Smith
November 1991

Location of negatives 5830 SE TAYLOR
Portland, Oregon
97215

28 of 34
2nd floor Service Corridor



Vetter, Herman House 1890
5830 SE Taylor
Portland, Multnomah County Oregon 97215

Photographer Patrick Smith
November 1991

Location of negative: 5830 SE Taylor
Portland Oregon
97215

29 of 34
Second floor bathroom



Vetter Herman House 1896
5830 SE TAYLOR
Portland, Multnomath County, Oregon

Photographer: Patrick Smith
November 1991

Location of negative: 5830 SE TAYLOR
Portland, Oregon 97215

30 of 34
Pocket doors separating Parlours



Vellen Herman House 1890

5830 SE Taylor

Portland Multnomah County, Oregon 97215

Photographer: Patrick Smith
November 1991

Location of negatives 5830 SE Taylor
Portland, Oregon
97215

31 of A 34
arched window northern elevation



Vette, Herman House
5830 SE TAYLOR
Portland, Multnomah County, Oregon 97215

Photographer: Patrick Smith
November 1991

Location of negative: 5830 SE TAYLOR
Portland, Oregon

32 OF 34
Povey window front parlour northern facade



Veter Hemman House 1890
5830 SE TAYLOR
Portland, Multnomah County, Oregon 97215

Photographer: Patrick Smith
November 1991

Location of negative 5830 SE Taylor
Portland, Oregon
97215

33 of 34
Lighting fixture from Parlour



Vetter, Herman House 1890
5830 SE Taylor
Portland, Multnomah County, Oregon 97215

Photographer Patrick Smith
November 1991

Location of Negative: 5830 SE Taylor
Portland Oregon
97215

34 of 34

front bedroom