



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Unknown, photo from The German-Russians by
Karl Stumpp, page 58

Date of photo: Unknown

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Handforming clay bricks in Russia.

Photo 1 of 11

SEP 13 1982



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Unknown, photo from Paradise on the Steppes, by
Joseph S. Height, page 121

Date of photo: Unknown

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Typical house in Strassburg, Russia; north of Odessa in the
Black Sea region.

Photo 2 of 11

SEP 13 1982



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Unknown

Date of photo: Unknown

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Original Goldade homestead, Goldade family and horses. View from south, southwest. The rocking chair is still in the house.

Photo 3 of 11

SEP 13 1982



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Jackie Sluss

Date of photo: 1979

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

South (front) facade, view from southeast.

Photo 4 of 11

SEP 13 1982



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Jackie Sluss

Date of photo: 1979

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View from southeast. Note exterior stair on east elevation.
View depicts current condition of house.

Photo 5 of 11

SEP 13 1982



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Jackie Sluss

Date of photo: 1979

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

View from northwest of west and north (rear) elevations.

Photo 6 of 11

SEP 13 1982



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Jackie Sluss

Date of photo: 1979

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Detail of window framing and attachment of clapboards.

Photo 7 of 11

SEP 13 1982



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Jackie Sluss

Date of photo: 1979

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Detail of window well on the north wall of the kitchen.

Photo 8 of 11

SEP 13 1982



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Jackie Sluss

Date of photo: 1979

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Interior of vorhausel and doorway to kitchen, view
from southwest.

Photo 9 of 11

SEP 13 1982



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Jackie Sluss

Date of photo: 1979

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Livingroom with turn-of-the-century wardrobe and dresser,
view from southeast.

Photo 10 of 11

SEP 13 1982



Johannes Goldade House
Rural Linton
Emmons County, North Dakota

Photo credit: Jackie Sluss

Date of photo: 1979

Location of negative: State Historical Society of North Dakota
North Dakota Heritage Center
Bismarck, ND 58505

Bedroom with turn-of-the-century bed, view from southeast.

Photo 11 of 11

SEP 13 1982