



Trinity Church

Thomaston, CT

D. Ransom Photo, 5/81

Negative: Connecticut

Historical Commission

CHURCH, FIRE STATION and

TOWN HALL, VIEW NORTH

Photograph 1 of 9



Trinity Church
Thomaston, CT
D. Ransom Photo, 5/81
Negative: Connecticut
Historical Commission
THE CROSSING, VIEW WEST
Photograph 2 of 9



Trinity Church

Thomaston, CT

D. Ransom Photo, 5/81

Negative: Connecticut

Historical Commission

PARISH HOUSE, VIEW SOUTH

Photograph 3 of 9



Trinity Church

Thomaston, CT

D. Ransom Photo, 5/81

Negative: Connecticut

Historical Commission

VIEW WEST

Photograph 4 of 9



Trinity Church

Thomaston, CT

D. Ransom Photo, 10/83

Negative: Connecticut

Historical Commission

VIEW WEST

Photograph 4A



Trinity Church

Thomaston, CT

D. Ransom Photo, 5/81

Negative: Connecticut

Historical Commission

CENTRAL ENTRANCE, VIEW

NORTH

Photograph 5 of 9



Trinity Church
Thomaston, CT
D. Ransom Photo, 10/83
Negative: Connecticut
Historical Commission
CENTRAL ENTRANCE, VIEW
NORTH
Photograph 5A



Trinity Church

Thomaston, CT

D. Ransom Photo, 5/81

Negative: Connecticut

Historical Commission

SOUTH ELEVATION, VIEW

EAST

Photograph 6 of 9



Trinity Church

Thomaston, CT

D. Ransom Photo, 10/83

Negative: Connecticut

Historical Commission

SOUTH ELEVATION, VIEW

EAST

Photograph 6A



Trinity Church
Thomaston, CT
D. Ransom Photo, 6/81
Negative: Connecticut
Historical Commission
SANCTUARY, VIEW NORTH-
WEST
Photograph 7 of 9



Trinity Church

Thomaston, CT

D. Ransom Photo, 5/81

Negative: Connecticut

Historical Commission

SANCTUARY, VIEW SOUTH-

EAST

Photograph 8 of 9



St. John's, Boonton



Church of the Reconciliation,
Webster



St. John's Episcopal Church
Youngstown, New York
1870

St. John's, Youngstown



St. Luke's, Charlestown

Trinity Church

Thomaston, CT

D. Ransom Photo, 6/81

Negative: Connecticut

Historical Commission

OTHER UPJOHN FRAME

CHURCHES

Photograph 9 of 9



Photo 1. General view, northwest.



Photo 2. South elevation, view northwest.



Photo 3. Work area north of church,
view southwest.



Photo 4. Sheet aluminum pieces shaped
to fit over board and battens.



Photo 5. (See Photo 1.) Last-minute preparations.



Photo 6. Fitting the piece into place.



Photo 7. At work on the belfry.
(See Photo 1.)

Photo 7. Star casting.



Photo 8. Star casting put into place with its flange overlapping the flat sheet.



Photo 9. Obverse of Photo 8. Spindles also are cast.



Photo 10. Belfry attached column,
showing hollow constuction.



Photo 11. Belfry attached column,
normal view.



Photo 12. Post with finials removed.

Photo 14. Post with new finials in place.



Photo 13. New cast finials.



Photo 14. Detail near west door on south elevation, showing the shaping of aluminum to fit the wood part.