Trinity Church
Thomaston, CT
D. Ransom Photo, 5/81
Negative: Connecticut
Historical Commission
CHURCH, FIRE STATION and
TOWN HALL, VIEW NORTH
Photograph 1 of 9

Trinity Church
Thomaston, CT
D. Ransom Photo, 5/81
Negative: Connecticut
Historical Commission
THE CROSSING, VIEW WEST
Photograph 2 of 9

Trinity Church
Thomaston, CT
D. Ransom Photo, 5/81
Negative: Connecticut
Historical Commission
PARISH HOUSE, VIEW SOUTH
Photograph 3 of 9

FORD

Trinity Church
Thomaston, CT
D. Ransom Photo, 5/81
Negative: Connecticut
Historical Commission
VIEW WEST
Photograph 4 of 9

Trinity Church
Thomaston, CT
D. Ransom Photo, 10/83
Negative: Connecticut
Historical Commission
VIEW WEST
Photograph 4A

Trinity Church
Thomaston, CT
D. Ransom Photo, 5/81
Negative: Connecticut
Historical Commission
CENTRAL ENTRANCE, VIEW
NORTH
Photograph 5 of 9

Trinity Church
Thomaston, CT
D. Ransom Photo, 10/83
Negative: Connecticut
Historical Commission
CENTRAL ENTRANCE, VIEW
NORTH
Photograph 5A

Trinity Church
Thomaston, CT
D. Ransom Photo, 5/81
Negative: Connecticut
Historical Commission
SOUTH ELEVATION, VIEW
EAST
Photograph 6 of 9

Trinity Church
Thomaston, CT
D. Ransom Photo, 10/83
Negative: Connecticut
Historical Commission
SOUTH ELEVATION, VIEW
EAST
Photograph 6A

THIRTY SUNDAY
266
271
455
287
HOLY HOLY HOLY

Trinity Church
Thomaston, CT
D. Ransom Photo, 6/81
Negative: Connecticut
Historical Commission
SANCTUARY, VIEW NORTH-
WEST
Photograph 7 of 9

Trinity Church
Thomaston, CT
D. Ransom Photo, 5/81
Negative: Connecticut
Historical Commission
SANCTUARY, VIEW SOUTH-
EAST
Photograph 8 of 9

St. John's, Boonton

Church of the Reconciliation, Webster

St. John's, Youngstown

St. Luke's, Charlestown

Trinity Church
Thomaston, CT
D. Ransom Photo, 6/81
Negative: Connecticut
Historical Commission
OTHER UPJOHN FRAME
CHURCHES
Photograph 9 of 9

Photo 1. General view, northwest.

Photo 2. South elevation, view northwest.

Photo 3. Work area north of church, view southwest.



Photo 4. Sheet aluminum pieces shaped to fit over board and battens.

Trinity Church
Thomaston, CT

Photo 5. (See Photo 1.) Last-minute preparations.

Photo 6. Fitting the piece into place.

Photo 7. At work on the belfry. (See Photo 1.)

Photo 7. Star casting.

Photo 8. Star casting put into place with its flange overlapping the flat sheet.

Photo 9. Obverse of Photo 8. Spindles also are cast.



Photo 10. Belfry attached column, showing hollow constuction.

Photo 11. Belfry attached column, normal view.

Trinity Church
Thomaston, CT

Photo 12. Post with finials removed.

Photo 13. New cast finials.

Photo 14. Post with new finials in place.

Photo 14. Detail near west door on south elevation, showing the shaping of aluminum to fit the wood part.