



86-7-192

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story

Date: December 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Vermont Route 7A,
Buildings #21, 22, 23, and 26
View looking south.

Photograph 1



86-7-184

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story

Date: October 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Vermont Route 7A,
Buildings #23, 26, and 27.

View looking north.

Photograph 2



88-A-102

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Leslie Goat

Date: August 1988

Negative filed at Vermont Division for
Historic Preservation

Description: Route 7 looking toward
Bennington from Center Shaftsbury; c.1900
View looking South

Photograph 3



86 A-192

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Baptist Parsonage (#1)

View looking west.

Photograph 4



86-7-192

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Galusha House (#2)

View looking west.

Photograph 5



86-7-192

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Barn (#2a), demolished
1988
View looking west.

Photograph 6



86-A-159

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Site of the Waldo
Tavern (#3)
View looking west.

Photograph 7



86-A-159

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story

Date: August 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Harlow and Margaret
Huntington House (#4)

View looking west.

Photograph 8



86-A-159

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Waldo Tavern Barn
(#4A)
View looking west.

Photograph 9



86-A-159

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Corn Crib (#4B)

View looking southeast.

Photograph 10



86-7-159

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Hog Barn (#4C)

View looking southeast.

Photograph 11



87-71

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: January 1987
Negative filed at Vermont Division
for Historic Preservation
Description: Walter Russel House
(#5)
View looking northwest.

Photograph 12



86-7-159

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Barn (#5B)

View looking west.

Photograph 13



86A-192

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story


Date: December 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Abiathar and Rachel
Waldo House (#6)

View looking southwest

Photograph 14



86A-159

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story

Date: August 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Barn/Garage (#6A)

View looking south.

Photograph 15



86-7-160

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Asa and Mary Whipple
House (#7)
View looking south.

Photograph 16



86 A-160

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story

Date: August 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Galusha Inn (#8)

View looking southwest.

Photograph 17



86A-160

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Galusha Inn Barn (#8A)

View looking southwest.

Photograph 18



86-7-160

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story


Date: August 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Cole-Stone House (#9)

View looking west.

Photograph 19



87A-1

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: January 1987
Negative filed at Vermont Division
for Historic Preservation
Description: Garage (#9A)

View looking northwest.

Photograph 20



LEGAL LOAD
LIMIT
24,000
POUNDS

86A-160

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story

Date: August 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Dr. J. G. Ross
House (#10), burned 1987.

View looking southwest.

Photograph 21



86A-192

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story

Date: December 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Rev. Caleb Blood House
(#13)

View looking ^{north} west.

Photograph 22



89A-1

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: January 1987
Negative filed at Vermont Division
for Historic Preservation
Description: Barn (#13c)

View looking northwest.

Photograph 23



86-7-161

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Myers House (#16)

View looking northeast.

Photograph 24




86A-161

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Barn (#16A)

View looking northeast.

Photograph 25



86-7-192

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Corn Crib (#16B)

View looking east.


Photograph 26



86-A-192

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Harrington House (#17)
View looking southeast.

Photograph 27



86A-161

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Barn (#17A)

View looking southeast.

Photograph 28



86-7-192

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Tourist Cabin (#18B)

View looking east.

Photograph 29



86-A-192

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Tourist Cabin (#18C)

View looking east.

Photograph 30



86-A-192

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Tourist Cabin (#18D)

View looking east.

Photograph 31



86A-192

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Tourist Cabin (#18E)

View looking east.

Photograph 32



86-A-192

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Tourist Cabin (#18F)

View looking east.

Photograph 33



87-A-1

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story

Date: December 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Tourist Cabin (#186)

View looking east.

Photograph 34



87A-1

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: January 1987
Negative filed at Vermont Division
for Historic Preservation
Description: Huntington-Spencer
House (#19)
View looking east.

Photograph 35



WEST MOUNTAIN
ANIMAL HOSPITAL

86-7-161

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story

Date: August 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Animal Clinic (#19B)

View looking southeast.

Photograph 36



86-7-160

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Baptist Church-Shafts-
bury Historical Society (#21)
View looking northeast.

Photograph 37



86-A-189

Center Shaftsbury Historic District
Shaftsbury, Vermont,
Credit: Kenneth Story
Date: December 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Old Galusha Inn Privy
(#21A)
View looking north.

Photograph 38



86 A-160

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Norman R. and C.
Amelia Douglass House (#22)
View looking east.

Photograph 39



86-A-160

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Brick Academy (#23)

View looking northeast.

Photograph 40



TOWN HOUSE

E5

86-7-160

Center Shaftsbury Historic District
Shaftsbury, Vermont
Crédit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Town House (#26)

View looking northeast.

Photograph 41



The
Country
Craft
Workshop

CLOSED

86-7-160

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: School House (#27)

View looking northeast.

Photograph 42



86 A-160

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: O'Dell House (#30)

View looking east.

Photograph 43



8677-159

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Herbert Daniels House
(#31)
View looking east.

Photograph 44



87A-1

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: January 1987
Negative filed at Vermont Division
for Historic Preservation
Description: Tourist Cabin (#34A)

View looking north.

Photograph 45



87-7-1

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Tourist Cabin (#340)

View looking south.

Photograph 46



86-7-159

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Jacob and Parthania
Galusha House (#36)
View looking east.

Photograph 47



86-A-159

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: August 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Jacob and Parthania
Galusha House (#36)
View looking northwest.

Photograph 48



86-7-159

Center Shaftsbury Historic District
Shaftsbury, Vermont

Credit: Kenneth Story

Date: August 1986

Negative filed at Vermont Division
for Historic Preservation

Description: Barn (#36A)

View looking southeast.

Photograph 49



86-7-184

Center Shaftsbury Historic District
Shaftsbury, Vermont
Credit: Kenneth Story
Date: November 1986
Negative filed at Vermont Division
for Historic Preservation
Description: Calf Barn (#36B)

View looking southeast.

Photograph 50