



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: facade, looking east.

Photograph Number: 1 of 17

AUG 13 1979

SEP 24 1979



HERITAGE

107

Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: detail of facade entrance

Photograph Number: 2 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: ground floor facade window detail.

Photograph Number: 3 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: 3/4 view of facade; colonial-revival beaded
weatherboard on gable end where once stood a two bay, two
story brick wing which functioned as a store and warehouse.

Photograph Number: 4 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/ASHP, Hall of Records, Dover, Delaware 19901

Description: south gable end; modern shed roof kitchen wing
to the left.

Photograph Number: 5 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: north gable end; note full return cornice;
much altered wing originally ended where chimney protrudes
from ridge.

Photograph Number: 6 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: stairhall; behind facade entrance door.

Photograph Number: 7 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: main staircase.

Photograph Number: 8 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: paneled fireplace endwall in present living
room.

Photograph Number: 9 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelon

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: wall cupboard in present living room.

Photograph Number: 10 of 17

AUG 13 1979

P 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: northwest corner of present living room;
exterior doorway on north gable end at right.

Photograph Number: 11 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979


Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: present living room door leading to
stairhall.

Photograph Number: 12 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: present living room cornice detail.

Photograph Number: 13 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Division of Historical & Cultural
Affairs, B/A&HP, Hall of Records, Dover, Del. 19901

Description: present dining room fireplace endwall with
federal-revival mantel; exterior doorway on south gable
end at right.

Photograph Number: 14 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: 3/4 view of facade of brick and store out-
building; note closed-up ventilator above window.

Photograph Number: 15 of 17

AUG 13 1979

SEP 24 1979



WINDER

Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979


Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: rear elevation of brick and stone outbuilding
refitted as a garage.

Photograph Number: 16 of 17

AUG 13 1979

SEP 24 1979



Name: John Lewden House (N-197)

Location: Vicinity of Christiana, New Castle County, Del.

Photographer: Dean E. Nelson

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: John Lewden; c. 1825; oil on canvas; artist
unknown; the namesake son or grandson of the builder of
the Lewden house; collection of the Historical Society of
Del. and reproduced through their courtesy.

Photograph Number: 17 of 17

AUG 13 1979

SEP 24 1979