

```
    John Fitch School Part II
    156 Bloomfield Avenue
    Windsor, CT
    View: Facade-1921 (L); 1929 add. (R)
```

Facing: NE
Conningham 12/85



```
2. John Fitch School
    156 Bloomfield Avenue
    Windsor, CT
```

View: Facade-1929 add. (R); 1921 (L) Facing: NW

Cunningham

12/85



- John Fitch School 156 Bloomfield Avenue Windsor, CT
- View: Facade close-up 1921 orig. school Facing:

Nagative on file: Conn. Hist. Comm.

12/85 Cunningham



View: Facade pavilion (1921) Facing: N

Cunningham



```
John Fitch School
156 Bloomfield Avenue
Windsor, CT
```

View: West elevation (1921) Facing: NE

Cunningham 12/85
Negative on file: Conn. Hist. Comm.



- 6. John Fitch School 156 Bloomfield Avenue Windsor, CT
  - View: Original rear entrance west elevation. Note docked gable roof with tile and sawn brackets. (1921)

Facing: E
Cunningham 12/85



View: Rear (north) elevation (1921) with rear of 1934 addition at left.

Facing: SE

Cunningham 12/85
Negative on file: Conn. Hist. Comm.



View: Entrance to 1929 addition Facing: N

12/85 Cunningham



View: East elevation of 1929 addition with 1934 addit n on right. Facing: NW

12/85 Cunningham Negative on file: Conn. Hist. Comm.



View: West elevation and part of 1934 addition on left. Facing: SE

Cunningham 2/86
Negative on file: Conn. Hist. Comm.



View: Interior of auditorium Facing: SW

Cunningham

Cunningham 2/86
Negative on file: Conn. Hist. Comm.



View: Interior gymnasium towards auditorium Facing: SE

Cunningham 2/86



View: Interior detail: typical staircase

Cunningham 2/86 Negative on file: Conn. Hist. Comm.



View: Interior typical classroom

Cunningham 2/86
Negative on file: Conn. Hist. Comm.