



Name: N-3935 Biddle House

Location: Biddle's Corner, vicinity St. Georges,

DE
Photographer: Cara Wise

Date: March, 1978

Location of Negative: Hall of Records, Dover, DE

Description: facade, looking south

Photograph Numbers 1

MAY 23 1978

DEC 8 1978



Name: N-3935 Biddle House

Location: Biddle's Corner, vicinity St. Georges,

Photographer: DE Cara Wise

Date: March, 1978

Location of Negative: Hall of Records, Dover, DE

Description: rear of house, looking north

Photograph Numbers 2

MAY 23 1978

DEC 8 1978



Name: N-3935 Biddle House

Location: Biddle's Corner, vicinity St. Georges,

Photographers DE Cara Wise

Date: March, 1978

Location of ~~Negative~~ Hall of Records, Dover, DE

Descriptions: detail of juncture of plank section with braced frame section. Note plank dimension and full dovetailed corners. (Brick nogging has been removed from portion of braced frame)

Photograph Numbers

3

DEC 8 1978

MAY 23 1978



Name: N-3935 Biddle House

Location: Biddle's Corner, vicinity St. Georges,
DE

Photographer: Cara Wise

Date: March, 1978

Location of Negative: Hall of Records, Dover, DE

Description: massive fire place in west wall of
plank section. Reduced in size to conform
to changes in the function of this portion
of the house.

Photograph Numbers 4

DEC 8

1978

MAY 23 1978