



San Ignacio Church

Albuquerque, New Mexico JUN 19 1979

photographer: Christopher Wilson

photograph date: April 17, 1978

negative: Historic Landmarks Survey,  
Albuquerque

view: west facade of church seen through  
archway on Edith Boulevard;  
camera looking east.

#1

AUG 21 1979



San Ignacio Church  
Albuquerque, New Mexico

JUN 19 1979

photographer: Christopher Wilson

photograph date: April 17, 1978

negative: Hist. Landmarks Survey, Albuquerque.

view: south and west facades of church

from church grounds; rectory in  
right background. Facing northeast

#2

AUG 21 1979



San Ignacio Church  
Albuquerque, New Mexico

JUN 19 1979

photographer: Christopher Wilson

photograph date: April 17, 1979

negative: Hist. Landmarks Survey, Albuquerque.

view: south and west facades of bell  
tower from church grounds.

Facing northeast.

#3

AUG 21 1979



San Ignacio Church  
Albuquerque, New Mexico

AUG 21 1979

JUN 19 1979

photographer: unknown

photograph date: ca. 1917

negative: Museum of Albuquerque

view: west facade of church from Edith  
Boulevard before 1926 remodeling  
and building of arch in photo #1.  
Facing east.