



#1 of ~~22~~ 33

MERINO HILL FARM, Route 524, Upper
Freshhold Twp., Monmouth County, New Jersey

Photographer: Rodney Meirs

Date: March 29, 1986

Negative located at Merino Hill

HOUSE AND HOMESTEAD AREA, looking north
across front field



#2 of ~~2~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Mairs

Date: March 29, 1986

Negative located at Merino Hill

FARMLAND. Looking northwest. House is at
approximate center of picture, hidden by
trees.



#3 of #233

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Meirs

Date: March 29, 1986

Negative located at Merino Hill

DRIVEWAY APPROACH TO HOUSE. Looking
west-northwest.



#4 of 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Meirs

Date: March 29, 1986

Negative located at Merino Hill

MAIN (SOUTH) FACADE ENTIRE. Looking north.



#5 of 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Meirs

Date: March 29, 1986

Negative located at Merino Hill

ENTRANCE DOORWAY AND FRONT PORCH,
Looking north.



#6 of 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Meira

Date: March 29, 1986

Negative located at Merino Hill

VIEW FROM FRONT PORCH, across lawn and
fields. Looking south-southeast.



#7 of ~~23~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Meirs

Date: March 29, 1986

Negative located at Merino Hill

MARBLE BUST OF GODDESS DIANA. Looking
northwest.



#8 of 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Meirs

Date: March 29, 1986

Negative located at Merino Hill

WEST FACADE ENTIRE; GLIMPSE OF NORTH FACADE.
Looking east-southeast. Smokehouse at left.
Remnant of lower retaining wall.



#9 of 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Meirs

Date: March 29, 1986

Negative located at Merino Hill

SMOKEHOUSE. Looking north.



#10 of ~~22~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Mairs

Date: March 29, 1986

Negative located at Merino Hill

NORTH FACADE ENTIRE. Looking south. Stone
foundations of icehouse at left.



#11 of 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Meirs

Date: March 29, 1986

Negative located at Merino Hill

FARM OFFICE / STOREHOUSE. Looking east
down driveway hill.



#12 of ~~2~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Meirs

Date: March 29, 1986

Negative located at Merino Hill

MAIN BARN (at left), STOREHOUSE (at right).
Looking east.



#13 of ~~2~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: Rodney Meirs

Date: March 29, 1986

Negative located at Merino Hill

QUAKER CEMETERY. Looking northeast.



#14 of ~~22~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: C. Malcolm Knowles

Date: September 15, 1986

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 1810 HOUSE: MAIN PARLOR, looking
north through fanfold doors.



#15 of ~~#~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: C. Malcolm Knowles

Date: September 15, 1986

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 1810 HOUSE: FIRST FLOOR HALL,
northern end.



#16 of ~~22~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: C. Malcolm Knowles

Date: September 15, 1986

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 1810 HOUSE: FIRST FLOOR HALL,
northern end, detail.



#17 of ~~2~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: C. Malcolm Knowles

Date: September 15, 1986

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 1810 HOUSE: STAIRWELL. Looking
directly upward from first floor.



#18 of ~~2~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: C. Malcolm Knowles

Date: September 15, 1986

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 1810 HOUSE: SECOND FLOOR HALL,
east wall.



#19 of 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: C. Malcolm Knowles

Date: September 15, 1986

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 1810 HOUSE: MASTER BEDROOM,
west wall.



#20 of ~~22~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: C. Malcolm Knowles

Date: September 15, 1986

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 1810 HOUSE: MASTER BEDROOM,
fireplace detail.



#21 of ~~22~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: C. Malcolm Knowles

Date: September 15, 1986

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 1810 HOUSE: BEDROOM (northwest),
west wall.



#22 of ~~22~~ 33

MERINO HILL FARM, Route 524, Upper Freehold
Twp., Monmouth County, New Jersey

Photographer: C. Malcolm Knowles

Date: September 15, 1986

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 1810 HOUSE: SECOND FLOOR HALL,
looking north.



#23 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING, First floor. Main room,
looking east. Shelves, dry sink,
bricked-in oven, fireplace.



#24 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING, First floor. Main room,
looking southeast. Fireplace, window,
Dutch door.



#25 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING, First floor. Main room,
looking north. Doorway at left into 1810
house. Stair; door to coldroom; door to
shed; shelves.



#26 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING, First floor. Main room,
north wall, looking down into coldroom.



#27 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING. Looking south through a
shed doorway toward profile of beehive
oven.



#28 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING. Interior of beehive oven. ↑



#29 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING, Cellar. Arches support-
ing oven and hearth.



#30 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING, Cellar. Iron firedoor
at opening into 1810 house.





#31 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING, Second floor. Southwest
bedroom, looking north.



#32 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING. Opening in wall of stairs
to attic. Traditionally a hiding place for
fugitive slaves on Underground Railroad.



#33 of 33 - MERINO HILL FARM, Route 524,
Upper Freehold Twp., Monmouth County, N.J.

Photographer: C. Malcolm Knowles

Date: January 12, 1987

Negative: C. Malcolm Knowles, Crosswicks,
New Jersey 08515

INTERIOR, 18c WING. Attic, looking north-
east. Beartrap, spinning wheel, etc.