



PLANT 153
NEW YORK
203

NY
P
O

Sitka spruce log

Blodgett Tract

Lincoln County, Oregon

Historic View 1918

University of Oregon Collection
Eugene, Oregon 97403

1 of 16



Warren Spruce Co.
Portland, Ore.
October 1, 1918.

Building Spruce Railroad XII

Lincoln County, Oregon

Historic View 1918

University of Oregon Collection
Eugene, OR 97403

2 of 16



Warren Spruce Co.
Portland, Ore.
October 1, 1915.

Building Spruce Railroad XII

Lincoln County, Oregon

Historic View 1918

University of Oregon Collection
Eugene, Oregon 97403

3 of 16



NO 37 IN SPRUCE CAMP TALEDGE MINE.

Building donkey sleds

Spruce Production Division Camp
Tolado, Lincoln County, Oregon

Historic View 1918

Oregon Historical Society photo

Negative number OR#118536

1230 SW Park St.

Portland, OR 97205

4 of 16



Erie shovel used to build spurs

Blodgett Tract

Lincoln County, Oregon

Historic view about 1926

Oregon Historical Society photo

Negative number ORH1 35988

1230 SW Park St

Portland, Oregon 97205

5 of 16



MANARY LOGGING CO.

MLCO 27

4

shay locomotives and donkey engines

Blodgett Tract

Lincoln County, Oregon

Historic view about 1926

Oregon Historical Society photo

negative number OR+1 35033

1230 SW Park St.

Portland, Oregon 97205

6 of 16



Spur 5 near beginning of nominated portion (1926)

Blodgett Tract
Lincoln County, Oregon

Ward Tonsfeldt photo, 1967
1363 NW Harmon Br
Bend, Oregon 97701

7 of 16
Looking Southwest

Neg. at Siuslaw NF
Covallis, OR
97339



Grade on spur 5 (1926)

Blodgett Tract
Lincoln County, Oregon

Ward Tonsfeldt photo, 1967
1363 NW Harmon Bv.
Bend, Oregon 97701

8 of 16
Looking South

Neg. at Siuslaw NF
Covallia, OR

97339



Cut on Spur 5 (1926)

Bladgett Tract

Lincoln County, Oregon

Ward Tonsfeldt photo, 1967

1363 NW Harmon Br

Bend, Oregon 97701

9 of 16

Looking Southwest

Neg. at Siuslaw NF

Covallis, OR

97339



Grade on Spur 5 (1926)
Looking SW
Blodgett Tract
Lincoln County, Oregon

Ward Tonsfeldt photo, 1967
1363 NW Harmon Br
Bend, Oregon 97701

10 of 16
Looking southwest
Neg. at Siöslaw NF
Convallis, OR
97339



grade on Spur 5 (1926)
Looking SW

Blodgett Tract
Lincoln County, Oregon

Ward Tonsfeldt photo, 1987
1363 NW Harmon Br
Bend, Oregon 97701

11 of 16

Looking Southwest
Neg. at Siuslaw NF
Covallia, OR
97339



Shackle and fair lead (1926)
Looking west

Blodgett Tract
Lincoln County, Oregon

Ward Tonsfeldt photo, 1987
1363 NW Harman Bv.
Bend, Oregon 97701

12 of 16
Neg. at Siuslaw NF
Convallis, OR
97339



High lead block (1926)
looking SE

Blodgett Tract
Lincoln County, Oregon

Ward Tonsfeldt photo, 1987
1363 NW Harmon Bv
Bend, Oregon 97701

13 of 16

Neg. at Siuslaw NF
Curvallis, OR

97339



Wheel at incline site (1926)
Looking West
Bledgett Tract
Lincoln County, Oregon

Ward Tansfeldt photo, 1987
1363 NW Harmon Bv
Bend, Oregon 97701

14 of 16
Neg. at Siuslaw NF
Covallis, OR
97339



Rail (1926)
Looking SE

Blodgett Tract
Lincoln County, Oregon

Ward Tansfeldt photo, 1987
1363 NW Harmon Bv
Bend, Oregon 97701

15 of 16

Neg - at Siuslaw NF
Corvallis, OR
97339



Donkey sled (1926)
looking west

Blodgett Tract
Lincoln County, Oregon

Ward Tonsfeldt photo, 1987
1363 NW Harmon Bv
Bend, Oregon 97701

16 of 16

Neg. at Siuslaw NF
Corvallis, OR
97339