

NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, ALABAMA 35801

VIEW: 1. Main House, north front & west side. Porch is circa 1940's. See photograph 21 and its notes. #1 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, ALABAMA 35801

VIEW: 2. Main house, north front, east end. # Z of Z



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, ALABAMA 35801

VIEW: 3. Entry and circa 1940's portico. #3 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, ALA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 4. Upper entry (apparently original) exiting from the second floor stainhall to the circa 1940's portico second level deck.

#4 of ZI



- HENRY HOSS HOUSE BLOUNTVILLE ROAD JONESBORO, TN PHOTOGRAPHER: HARVIE P. JONES, FAIA
- NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801
- VIEW: 5. Typical brickwork, south wall, east end, main north wing. Note pencilling traces.
- #5 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, ALA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 6. Looking N.E., Kitchen wing & porch in foreground said to be added circa 1865 (Alexandra Hoss). #6 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, ALA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 7. Looking N.N.W. from beside the barn. Compare with historic photo 20. # 7 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 8. Springhouse. Second floor is storage. #8 チェ



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 9. S.E. Corner of Springhouse. Vee-corner notching.



NEGATIVES: JONES & HERRIN, ARCHITECTS, ALA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 10. Barn, background, circa 1914 (according to Alexandra Hoss).

10 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 11. Stair looking east. # 11 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 12. Door to N.E. parlor from entry hall. # 12 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 13. First floor N.E. mantel.



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801


VIEW: 14. First floor N.W. mantel. # 14 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 15. Second floor N.E. mantel & original closet (based on construction details).

15 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, ALA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 16. Second floor N.E. Mantel & original closet (based on construction details). # 16 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 17. Second floor N.W. mantel. #17 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 18. Second floor door from stairhall to N.E. bedroom.


18 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 19. Rimlock in second floor N.W. bedroom. (Mid 19th century "Walker".)

19 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, AIA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 20. Rear view looking N.N.W.(historic photo). Compare with 1982 photo 7. # 20 of 21



NEGATIVES: JONES & HERRIN, ARCHITECTS, ALA 104 JEFFERSON STREET HUNTSVILLE, AL 35801

VIEW: 21. Front view looking S.W. Ca. 1912 porch, in 1928. $\# \ge 1 \text{ of } \ge 1$