



COTTON HALL

RINGLER'S DANCING ACADEMY

MOTOR COMPANY GARAGE

MORELAND TRUCKS  
TUBING  
CARS  
TRUCKS

MCCRAKEN MOTOR C  
MORELAND  
CUMMINS  
VEH  
TRUCKS

COVERED ENTRANCE



Cotillion Hall  
406 SW 14th Avenue  
Portland, Multnomah  
County, Oregon

MAR 9 1979

1 of 7 JAN 29 1979

Historic View (Ca 1918)  
Oregon Historical Society  
1230 SW Park Avenue  
Portland, Oregon 97205

1. Cotillion Hall
2. Portland OR
3. Photog. Unknown
4. Date: c. 1918
5. Ore. Hist Soc. (Neg.)
6. Ext. looking S.E.
7. No. 1



1. Cotillion Hall
2. Portland OR
3. Mike Cushman  
(Photoq.)
4. Nov. 1978
5. Scott Kreiger (Neg.)  
Portland OR
6. Ext. looking  
S.E.
7. No. 2

Cotillion Hall  
406 SW 14th Avenue  
Portland, Multnomah  
County, Oregon

MAR 9 1979

JAN 29 1979

2 of 7  
North and West elevations  
Mike Cushman photo 1978  
Scott Kreuger, negative  
Portland, Oregon



Cotillion Hall  
406 SW 14th Avenue  
Portland, Multnomah  
County, Oregon

MAR 9 1979

3 of 7      JAN 29 1979  
Musician's balcony, 3rd  
floor dance hall  
Mike Cushman photo 1978  
Scott Kreuger Portland OR

1. Cotillion Hall
2. Portland OR
3. Mike Cushman (Photo)  
Portland OR
4. Nov. 1978
5. Scott Kreuger (Neg.)  
Portland OR
6. 3rd Fl. Dance Hall  
looking NE @  
"Musician's Balcony"
7. No. 3





Cotillion Hall  
406 SW 14th Avenue  
Portland, Multnomah  
County, Oregon

MAR 9 1979

4 of 7

Balcony, west end of 3rd  
floor dance hall  
Mike Cushman photo, 1978  
Scott Kreuger, negative

Portland, Oregon

JAN 29 1979

1. Cotillion Hall
2. Portland OR
3. Mike Cushman (photoq.)  
Portland OR
4. Nov. 1978
5. Scott Kreuger (Neg.)  
Portland OR
6. 3rd Fl. Dance Hall  
looking W. towards  
Balcony
7. No. 4





Cotillion Hall  
406 SW 14th Avenue  
Portland, Multnomah  
County, Oregon

MAR 9 1979

5 of 7

Looking toward south  
wall, 3rd floor dance  
hall

Mike Cushman photo, 1978

Scott Kreuger, negative  
Portland, Oregon

JAN 29 1979

1. Cotillion Hall
2. Portland OR
3. Mike Cushman (Photoq.)  
Portland OR
4. Nov. 1978
5. Scott Kreuger (Neg.)  
Portland OR
6. 3rd Fl. Dance Hall  
looking S.W.
7. No. 5



1. Cotillion Hall
2. Portland OR
3. Mike Cushman (Photoq.)
4. Nov. 1978
5. Scott Kreuger (Neg.)  
Portland OR.
6. 3rd Fl. Dance Hall  
looking S.W. @  
Balcony rail
7. No. 6

Cotillion Hall  
406 SW 14th Avenue  
Portland, Multnomah  
County, Oregon

MAR 9 1979

6 of 7  
Balcony stairs and railing,  
west end 3rd floor dance hall  
Mike Cushman, photo 1978

Scott Kreuger, negative  
Portland, Oregon

JAN 29 1979



Cotillion Hall  
406 SW 14th Avenue  
Portland, Multnomah  
County, Oregon

MAR 9 1979

7 of 7

Typical console with  
masque, side walls, 3rd  
floor dance hall

Mike Cushman photo, 1978

Scott Kruger negative  
Portland, Oregon

JAN 29 1979

1. Cotillion Hall
2. Portland OR
3. Mike Cushman (Photoq.)
4. Nov. 1978
5. Scott Kreiger (Neg.)  
Portland OR
6. 3rd Fl. Dance Hall  
looking S. @  
typical console
7. No. 7