



Name: Agricultural Buildings and Complexes in Mill Creek
Hundred, 1800-1840, Springer Farm (N-1110)

Location: Box 198, Limestone Road, Hockessin, Delaware 19707

Photographer: Valerie Cesna

Date: June 1986

Location of Negative: Bureau of Archaeology and Historic
Preservation, Dover, Delaware

Description: Dwelling, view from southeast

Photograph Number: 14



Name: Agricultural Buildings and Complexes in Mill Creek
Hundred, 1800-1840, Springer Farm (N-1110)

Location: Box 198, Limestone Road, Hockessin, Delaware 19707

Photographer: Valerie Cesna

Date: June 1986

Location of Negative: Bureau of Archaeology and Historic
Preservation, Dover, Delaware

Description: Barn, view from south

Photograph Number: 15