

- Photo by Robert Seinmann October, 1983 Negative in possession of photographer Front Facade, Commercial Street looking Southeast
- Photo #1



Photo by Robert Steinmann October, 1983 Negative in possession of photographer Side Facade, 12th Street looking East



Photo by Robert Steinmann Negative In possession of photographer Front facade, Commercial Street looking Southeast



- Photo by Robert Steinmann Negetive in possession of photographer Front Facade, Commercial Street looking Southeast
- Photo #4



Photo by Robert Steinmann Negative in possession of photographer Interior painting by Joe Knowles, Side wall Theater bacony



Photo by John Goodenberger Negative in possession of photographer Upper window, S.W. cormer tower looking East, 12th Street



Photo by John Goodenberger Negative in possession of photographer Interior lighting fixture, Lobby of Balcony



Photo by John Goodenberger Negative in possession of photographer Interior lighting fixture, Ramp to Balcony



Photo by Robert Steinmann Negative in possession of phtographer Interior lighting fixture, cetral chandelier, Theater



Photo by John Goodenberger Negative in possession of photographer Interior moulding, upper wall Theater