



Rice-Gates House
308 SE Walnut St.
Hillsboro, Washington Co, Ore.
1 of 7 - Historic view, c.
1905. North and west elevation

showing carriage house or
garage in rear and original
wood roof cresting, now miss-
ing.

JUL 28 1980

Photographer unknown.

George Champlin
308 SE Walnut St.
Hillsboro, OR 97123

~~SEP 8 1980~~



Rice-Gates House
308 SE Walnut St.
Hillsboro, Washington Co, OR
2 of 7 - Historic view, c.
1910. West and south eleva-
tions, showing use of awnings
at window openings, covered
walkway to garage.

Photographer unknown.

George Champlin
308 SE Walnut St.
Hillsboro, OR 97123

JUL 28 1980

SEP 8 1980



Rice-Gates House
308 SE Walnut St.
Hillsboro, Washington Co, OR
3 of 7 - Looking SE from in-
tersection of SE Walnut St.

and S. Second Ave. at north
and west elevations, showing
overall integrity of property.
Note loss of upper chimney
stack and solid, shingle-cov-
ered railings for north porch
staircase. Garage is now on
separate holding and is not
included in area nominated.
George Champlin photo, 1979
308 SE Walnut St.
Hillsboro, OR 97123

0861 8
SEP 8
PES

JUL 28 1980



Rice-Gates House
308 SE Walnut St.
Hillsboro, Washington Co, OR
4 of 7 - North (front) eleva-
tion from SE Walnut St.

George Champlin photo, 1979
308 SE Walbut St.
Hillsboro, OR 97123

JUL 28 1980

0861 8
SEP DES



Rice-Gates House
308 SE Walnut St.
Hillsboro, Washington Co, OR
5 of 7 - West elevation, showing side porch.

George Champlin photo, 1979
308 SE Walnut St.
Hillsboro, OR 97123

JUL 28 1980

08618

DES



Rice-Gates House
308 SE Walnut St.
Hillsboro, Washington Co, OR
6 of 7 - South (rear) eleva-
tion showing repairs to

JUL 28 1980

shingle-covered substructure
of sun porch in progress.

George Champlin photo, 1979
308 SE Walnut St.
Hillsboro, OR 97123

08618

SEP



Rice-Gates House
308 SE Walbut St.
Hillsboro, Washington Co, OR
7 of 7 - East and north eleva-
tions.

JUL 28 1980

George Champlin photo, 1979
308 SE Walnut St.
Hillsboro, OR 97123

SEP

8 1980