	499
NPS Form 10-900 (Rev. 10-90)	RECEIVED 4 0MB No. 1024-0018
United States Department of the Interior National Park Service	APR 1 9 1994
NATIONAL REGISTER OF HISTORIC PLACES REGISTRATION FORM	INTERAGENCY RESOURCES DAVID NATIONAL PARK SERVICE
1. Name of Property	
historic name Lanford, William, House	
other names/site number Lanford-Simpson Hou	ise; Pleasant Hill Farm
2. Location	:=E===================================
street & number 7400 (AKA 7270) Old Madison	Pike not for publication N/A
city or town <u>Huntsville</u> state <u>Alabama</u> code <u>AL</u> count	vicinity <u>N/A</u> cy <u>Madison</u> code <u>089</u> zip code <u>35806</u>
3. State/Federal Agency Certification	:
See continuation sheet for additional commen- <i>Autosum</i> Signature of certifying official <u>Alabama Historical Commission (State Histor</u> State or Federal agency and bureau	<u>April 12, 1994</u> Date ric Preservation Office)
See continuation sheet for additional comments	_ does not meet the National Register criteria. (ents.)
Signature of commenting or other official	Date
State or Federal agency and bureau	
4. National Park Service Certification	
I, hereby certify that this property is: 	al Register
Signature of Keeper	$\frac{5 \cdot 20 \cdot 74}{\text{Date of Action}}$

USDI/NPS Registration Form Property Name Lanford, William House County and State Madison County, Alabama

5. Classification Ownership of Property (Check as many boxes as apply.) X private public-local public-State public-Federal Category of Property (Check only one box.) building(s) X district site structure object

Page #2

Number of Resources within Property

Contributing	Noncont	ributing
4	2	buildings
0	0	sites
0	_1	structures
0	0	objects
4	3	Total

Number of contributing resources previously listed in the National Register ____N/A___

Name of related multiple property listing (Enter "N/A" if property is not part of a multiple property listing.) N/A

⋍∊ _⋽ ⋠⋭⋳⋠⋭⋳⋧⋐⋧⋹⋠⋕⋭⋭⋠⋭⋈⋒⋢⋹⋠⋪⋹⋕⋽⋾⋩⋍⋍⋳⋠⋡⋈⋽⋽⋤⋻⋈⋕⋭⋍⋠⋢⋭⋝⋊⋍⋶⋾⋶⋵⋩⋎⋶⋤⋤⋭⋵⋡⋧⋶⋻⋵⋵⋉⋳⋋⋹⋞⋹⋭⋈⋓⋧⋳⋇⋭⋇⋠⋵⋾
6. Function or Use

Historic	Functions	(Enter	categories	from	instructions)	

-

Cat:	Domestic	Sub:	Single Dwelling
	Agriculture/Subsistence		Agricultural Outbuilding
Current F	unctions (Enter categories	from in	structions)
Cat:	Domestic	Sub:	Single Dwelling

	State <u>Madison County, Alabama</u>	Page #3
		世史로부분호수류물호흡적원호원국고로로
7. Descripti	ÌON ■₩₩₽₩₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽₽	性系在实现的名字和名字和名字在字中的名字
Architectura	al Classification (Enter categories from instructions)	
	k Revival	
Feder	ral	* *
_ ,		
Materials (E	Enter categories from instructions)	
	dation <u>brick</u>	
	Coppers wood	t
Waiis		
other	r wood	
Name the Da		wation sheet (s)
Narrative De	escription (Describe the historic and current condition on contin	nuation sneet/s.)
3. Statement	t of Significance	
	National Register Criteria (Mark "x" in one or more boxes for the y for National Register listing)	e criteria qualifyin
A	• • • • • • • • • • • • • • • • • • • •	nt contribution to
	the broad patterns of our history.	
В	Property is associated with the lives of persons significant :	in our past.
	Toperty is associated with the first of persons significant.	
<u> </u>	Property embodies the distinctive characteristics of a type, p	period, or method of
<u> </u>	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses	period, or method of high artistic
<u>x</u> c	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity	period, or method of high artistic
<u>x</u> c	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction.	period, or method of high artistic y whose components
	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction.	period, or method of high artistic y whose components
D	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history.	period, or method of high artistic y whose components
D Criteria Con	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.)	period, or method of high artistic y whose components tant in prehistory o
D	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave.	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave.	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave.	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property.	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C D E F G	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C C D C D E F G Areas of Sig	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions)	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C C D C D E F G Areas of Sig	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions) ecture	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C D E F G Archite	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions) ecture	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C D E F G Areas of Sig <u>Archite</u> 	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions) ecture	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C D E F G Areas of Sig <u>Archite</u> 	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions) ecture	period, or method of high artistic y whose components tant in prehistory o
D Criteria Con A B C D E F G Areas of Sig <u>Archite</u> 	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpos removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions) ecture	period, or method of high artistic y whose components tant in prehistory o
D Criteria Com A B C D E F G Areas of Sig <u>Archite</u> Period of Si	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpose removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions) ecture	period, or method of high artistic y whose components tant in prehistory of ses.
D Criteria Com A B C D E F G Areas of Sig <u>Archite</u> Period of Si	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpose removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions) ecture ignificance c. 1850 c. 1920	period, or method of high artistic y whose components tant in prehistory of ses. e past 50 years.
D Criteria Con A B C D E F G Areas of Sig <u>Archite</u> Period of Si	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpose removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions) ecture	period, or method of high artistic y whose components tant in prehistory of ses. e past 50 years.
D Criteria Con A B C D E F G Areas of Sig <u>Archite</u> Period of Si Significant	Property embodies the distinctive characteristics of a type, property embodies the distinctive characteristics of a type, property construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpose removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions) ecture ignificance c. 1850 c. 1920 Person (Complete if Criterion B is marked above) N/A	period, or method of high artistic y whose components tant in prehistory of ses. e past 50 years.
D Criteria Con A B C D E F G Areas of Sig <u>Archite</u> Period of Si Significant	Property embodies the distinctive characteristics of a type, p construction or represents the work of a master, or possesses values, or represents a significant and distinguishable entity lack individual distinction. Property has yielded, or is likely to yield information import history. nsiderations (Mark "X" in all the boxes that apply.) owned by a religious institution or used for religious purpose removed from its original location. a birthplace or a grave. a cemetery. a reconstructed building, object, or structure. a commemorative property. less than 50 years of age or achieved significance within the gnificance (Enter categories from instructions) ecture ignificance c. 1850 c. 1920	period, or method of high artistic y whose components tant in prehistory of ses. e past 50 years.

USDI/NPS Registration Form Property Name_Lanford, William, House County and State_Madison County, Alabama	Page #4
9. Major Bibliographical References	
(Cite the books, articles, and other sources used in preparing this form on on continuation sheets.)	
Previous documentation on file (NPS) N/A preliminary determination of individual listing (36 CFR 67) has been reque previously listed in the National Register previously determined eligible by the National Register designated a National Historic Landmark recorded by Historic American Buildings Survey # recorded by Historic American Engineering Record #	sted.
Primary Location of Additional Data _X_State Historic Preservation Office Other State agency Federal agency Local government University Other Name of repository:	
10. Geographical Data	
Acreage of Property <u>112.03 acres</u> UTM References (Place additional UTM references on a continuation sheet) Zone Easting Northing Zone Easting Northing 1 <u>16</u> 527350 <u>3841930</u> 3 <u>16</u> 528140 <u>3841000</u> 2 <u>16</u> 528190 <u>3841930</u> 4 <u>16</u> 527520 <u>3840940</u> See continuation sheet.	
Verbal Boundary Description (Describe the boundaries of the property on a cont:	inuation sheet.)
Boundary Justification (Explain why the boundaries were selected on a continuat	
11. Form Prepared By	
name/title_Harvie P. Jones, FAIA and Jeannette and Diane Simpson organization_N/A date_	
street & number_104 Jefferson St telephone	
city or town_Huntsville	

JSDI/NPS Registration Form Property Name Lanford, William, House County and State Madison County, Alabama Page #5 Additional Documentation Submit the following items with the completed form: ٩. Continuation Sheets 1aps A USGS map (7.5 or 15 minute series) indicating the property's location. A sketch map for historic districts and properties having large acreage or numerous resources. Photographs Representative black and white photographs of the property. Additional items (Check with the SHPO or FPO for any additional items) Property Owner (Complete this item at the request of the SHPO or FPO.) name __Oscar G. Simpson, M. D. & Jeannette Simpson_____ street & number_7400 (AKA 7270) Old Madison Pike______ telephone_(205) 830-5592; 837-6250

NPS Form 10-900-a (8-86)	RECEIVED 4
United States Department of the Interio National Park Service NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET Section <u>7</u> Page <u>1</u>	APR 19 1994 INTERAGENCY RESOURCES DIVISION NATIONAL PARKWERVIOE, House name of property Madison County, Alabama county and State
ニーニーニーの「「「「」」」の「「」」の「「」」の「「」」の「「」」の「「」」の	

ARCHITECTURAL DESCRIPTION (1)

The two-story, rectangular, three bay, gable-roofed 1850 William Lanford House is clapboarded Greek Revival with all its major elements of wood, including the tetrastyle pedimented portico with its heavy, two-story, boxed, tapered columns and pilasters. The foundation walls, portico base and four exterior chimneys are of brick. The main roof is side gabled. An undated photo of perhaps 1920-1950 shows that the torus moulds of the four portico columns were of moulded brick on a brick floor and plinths, which is probably the original condition since the use of large moulded bricks would have been unlikely in a post-1850 repair. Those bricks were probably stuccoed originally to blend them with the form of the column shaft. The moulded bricks eventually deteriorated and have been replaced recently with carved linesstone in the same finished profile (and approximate effect) as the moulded, stuccoed brick torus and plinth. The brick steps and cheekwalls are also being repaired to match the apparent original condition shown in the old photograph and in site evidence.

A cantilevered balcony with a typical 1800-1850 type balustrade (round top-rail, thin rectangular balusters) is cantilevered over the entry, under the portico.

While the house is well-proportioned with properly heavy Greek Revival elements, there are several Federal Period holdovers present which are successfully incorporated; the trabeated entry with its heavy pilasters, architrave, frieze and cornice enframes a delicate sunburstpattern elliptical fanlight with slender wood muntins. The four windows of the principal facade are three-part derivations (without fanlights) of the Venetian or "Palladian" window used in the late 18th and early 19th century. The end-gables of the main roof are cut flush to the wall (except for a cornice-mould) in the Federal Period manner rather than having typical Greek Revival projecting gable eaves. The balustrade at the portico balcony is very delicate, and there are mortise-traces in the portico pilasters and corner columns indicating that a similar delicate balustrade was once at each side (but not the front) of the portico platform.

The above mortise-traces tend to confirm that the portico floor was originally brick because there is a mortise for a bottom rail. If the portico floor had been wood, the balusters would most frequently have been mortised into the floor, as they are at the extant balcony.

The entry is a pair of doors with the above described fanlight. The double-door balcony entry is trabeated similarly to the entry below with a necessarily shorter entablature due to the proximity of the portico soffit.

At some point probably in the 1920-1950 period per the architectural evidence the solid paneled double front doors were replaced with 12-light glass-paneled wood doors to admit more light into the entry. The original pair of single-panel Greek Revival doors remains as evidence at the rear doorway, although 20th century 15-light glass doors have been added on the exterior face.

The four brick end-chimneys have typical stepped-out corbels at their bases (on the wide side only). The chimneys have sloped-brick shoulders rather than the typical 19th century stepcorbel shoulders. The shoulders show, in the mortar joints, evidence that they were rebuilt at NPS Form 10-900-a (8-86)

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

Section 7 Page 2

Lanford, William, House	`
name of property	• <u>••••</u> •••••••••••••••••••••••••••••••
Madison County, Alabama	
county and State	

some point in this atypical fashion. Lime mortar was not strong enough to hold bricks on a steep slope, so it is unlikely this is an original detail and it is contrary to 19th century practice.

The chimney-stacks stand clear (by about 5 inches) of the clapboard gables, above the shoulders; a typical 19th century fire safety measure when ceramic flue-liners did not exist and a chimney fire could shoot 2000 degree air through an eroded or cracked brick-flue joint into the wooden attic and roof shingles. While the 3 bay south front facade is regular and well-proportioned, the gable end walls take a strictly functional approach, as was usual in the 19th (and other) centuries. The gable eaves are clipped and there is only one upper window at each gable to light the two second floor rooms at each gable. Wall space was tight by the chimneys at the smaller rear bedrooms, so end-wall windows were omitted there. An irregular window pattern on the side walls is the result. Each gable shows a trace of an attic window, now covered with clapboards.

The roof pitch is a fairly low +/- 20 degrees, usual and proper for the Greek Revival style, and a significant lowering from the previous Federal Period roof pitch of about 30 degrees or steeper.

To the rear northwest corner of the house is appended a 2 room and bath clapboard addition that appears to date from the mid-20th century. The historic photograph shows a cast iron balustrade around the flat roof of the south bay of this addition (photo #2) presumably indicating that this was a viewing deck. The balustrade is now gone. The rear northeast corner of the house has a small laundry and one car shelter of a similar time period. The rear of the house has a large glazed verandah that may have once been open but is probably not original. A large 20th century raised brick terrace parallels this room. The terrace overlooks a modern garden and lawn area to the north, containing a modern gazebo and two 20th century frame utility buildings. These resources count as 1 noncontributing structure and 2 noncontributing buildings. The three barns to the northwest, which are contributing resources, are described below.

While the basic plan of the house is a typical center hall layout with two rooms per side per floor, the plan has an unusual twist. The hall is very wide, about 15 feet by 35 feet deep, and can be completely opened to the adjoining parlor and dining room by means of multi-panel, tall (original) folding doors (folding walls in effect) on each side of the hall, creating a large T-shaped space of about 18 x 52 feet plus the "tee" space of about 15 x 17 feet containing the open stair. This is an open space of about 1,200 square feet, which must have been meant for, and highly suited for, expansive entertainment of large numbers of guests. Yet the large space could be divided into normal size rooms at will (see enclosed floor plan).

In addition to the formal rooms, the first floor northeast room must originally have been intended for service since it contains an original concealed narrow ell plan service stair to the second floor bedrooms. This room also adjoins the southeast dining room. The separate kitchen building was likely not too far from the northeast corner of the main house but no evidence or tradition of it is known. NPS Form 10-900-a (8-86)

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

Section _7_ Page _3_

Lanford, William, House	e``
name of property	
Madison County, Alabama	A

The first floor northwest room is now a study and perhaps originally served a similar purpose since there were 4 bedrooms on the second floor.

A partial basement is under the rear half of the house. It retains its split-lath and hair plaster ceiling, plastered brick walls, a board-and-batten door and a 19th century wood barred vent, all typical of mid-19th century construction.

The south (front) facade is strikingly similar to the 1851 Greek Revival Robert Donnell house about 15 miles away in Athens, Alabama (2). This resource is already listed on the National Register. Moreover, the very unusual mantels in the Lanford House are virtually identical to those in the Donnell House and to those in a mid-19th century nonhtwest addition to the nearby National Register Hurn-Thach House (about 12 miles west) in Mooresville, Alabama (3). These mantels have very large, flamboyant, non-Greek Revival cyma-recta profile pilasters and architraves that are surely the invention of a local craftsman. There may be a relationship or at least influence among these three nearby and contemporary structures regarding the craftsmen and/or the owners. These unusual mantels have not been observed by the writer in other houses or in handbooks.

The doors throughout the 1850 rooms are the typical Greek Revival type with 2 vertical panels, a battered wide jamb face trim with rectangular backband about $1/2 \ge 2$ inches, "Greek ear" architrave projections and flat architrave tops as opposed to the slightly gabled ones seen in more elaborate Greek Revival door frames (4). A pair of single panel Greek Revival doors at the second floor, front center hall opens onto a small balcony that is under the portico.

The floors are typical for the 1850s and earlier with dense grained, mostly edge-grain 5.5 to 7 inch random width heart pine, 5/4 inch thick tongue and grooved, face-nailed with 2 cut nails (ell-head "sprigs") at each joist. The joists are about 2 feet on centers per usual 19th century practice.

The walls and ceilings are plaster. There are no wall cornices in any rooms, which is usual. Examples of pre-1860 wall cornices are almost non-existent. Only 2 rooms (in 2 different houses) are known in this area. Apparently wallpaper friezes were used in lieu of wall cornices (where anything was used) based on some hard evidience (2 houses) and literature and illustrations of the period.

Both the main and service staircases have the simple balustrade design of the 1800-1860 period consisting of a round rail of about 2.25" in diameter and slender rectangular balusters, two per tread, of about 5/8 x 1.25 inches with the wide sides parallel to the treads. The newels are similar to Tuscan colonettes but with an 1850s bulbous bottom to the shaft. The tread ends are devoid of any scrolls or other such elaborations that was fashionable in the Federal Period and the earlier part of the Greek Revival period. This is undoubtedly a stylistic desire for Greek simplicity and mass rather than an economic choice as this was an ambitious house.

The south front door has a Federal Period design feature, an elliptical sunburst leaded glass fanlight which is encased in a Greek Revival architrave while the rear (north) entry has a

OMB No. 1024-0018

NPS Form 10-900-a (8-86)

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

Section 7 Page 4

Lanford, William, House	×
name of property	
Madison County, Alabama	
county and State	

typical rectangular toplight that now contains a Victorian-looking faceted and leaded glass innfill over the Greek Revival transom.

The secondary room mantels are typical of the Greek Revival period. They are simple rectangular pilasters and architraves with only a few heavy moulds at the pilaster plinth tops and bed moulds at the pilaster capitals and mantel shelves. Some mantels have the "Greek Ear" and battered pilaster motif like the door frames, capped by a simple mantel shelf.

Mid-twentieth century baths and closets have been inserted in several rooms (see the enclosed floor plans).

About 500 feet northwest of the house is a neat row of 3 barns of as many sizes and types which appear by their framing to be early 20th century. Each barn is for a different purpose. The small center barn appears to be a granary, with several planked compartments with raised wood floors, off an equipment side-aisle for wagons to bring in the feed stock to be unloaded into the appropriate compartment. The west barn is the cattle barn and has a side shed plan containing hay racks for feeding. This barn has an ingenious arrangement wherein the hay can be pitched down from the loft into the feeding racks, which are accessible to cattle from both inside the barn and under the side shed. The east barn is the horse or mule barn, with stalls on each side of a center aisle. Each barn has a loft. All three barns have a very slight gambrel roof of modern galvanized iron and vertical board siding, some of which is up to 19" wide. This, plus the sizes of the framing members (about 1/8" less than "nominal" and rotarysawn) supports the probable c. 1900-1930 dates.

North of and behind the house are 3 small, noncontributing resources--a gazebo and 2 clapboard utility buildings that appear to be less than 50 years old.

The William Lanford House is located between the fast growing cities of Huntsville and Madison. About 150 feet east of the house, at its east property line, is an enormous earth excavation project in progress, in preparation for construction of an addition to the very large Huntsville Research Park which already contains dozens of large structures of up to 6 floors and several million square feet total. At least one city map indicates the proposed taking of the 1850 Lanford House and property for the research park. The two lane country road in front of the house is scheduled to become four lane. The house is thus endangered by this huge development only 150 feet away (5).

Furthermore, the city of Huntsville has also proposed a series of "Greenway Plans." One of these proposed greenways, the Indian Creek Greenway, will border the creek which lies on the western border of the William Lanford property. This greenway will take away from the natural state of the William Lanford House because "asphalt and concrete are the two preferred surface materials for multi-use trails." The city plans to cut trees, disturb a wetland along the William Lanford property and provide asphalt and concrete trails along the border of the property (6).

OMB No. 1024-0018 NPS Form 10-900-a (8 - 86)United States Department of the Interior National Park Service NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET Section _7 Page _5_ Lanford, William, House name of property Madison County, Alabama county and State ENDNOTES (1) Prepared by Harvie P. Jones, FAIA, Huntsville, AL. (2) Robert Donnell House: Annotated photograph, Vol. #8, Harvie P. Jones; FAIA Historical Photograph Collection, Huntsville, AL. Hurn-Thach House, Annotated photograph, Vol. #40, Harvie P. Jones; FAIA Historical (3) Photograph Collection, Huntsville, AL.

(4) The Beauties of Modern Architecture, Minard Lafever, 1838.

(5) Harvie P. Jones and Diane Simpson.

(6) Diane Simpson.

OMB No. 1024-0018

NPS Form 10-900-a (8-86)

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

Section 8 Page 6

Lanford, William, House name of property	
Madison County, Alabama	

STATEMENT OF SIGNIFICANCE

The 1850 Lanford House is eligible for the National Register under Criterion C for its architecture. The property is a good and intact example of the transitional Federal/Greek Revival style of architecture. It retains virtually all of its original features. The few 20th century insertions (baths, kitchen) and additions are done in a manner as to not detract from the original design. The front facade with its central portico is well-proportioned and presents a strong and dignified image.

The arrangement of the primary interior spaces is unique in this area in that it incorporates 2 original folding walls whereby the 15 foot wide central hall can be completely opened to the adjoining parlor and dining room to form a contiguous space of about 1,200 square feet for large entertainments, as well as for better summer ventilation.

The Lanford House is further significant in Madison County in that it is the only known surviving clapboarded, large Greek Revival house in the county. This single survivor of its type is endangered by the growth of an adjoining industrial park. The Lanford property retains 3 contributing early 20th century barns, each designed for a different and specific use. Since barns are generally not needed in today's agricultural practices, they are rapidly disappearing due to lack of need and maintenance. The 3 Lanford barns are well-maintained examples of a building type that, at the present rate of attrition in Madison County, will be largely gone in another 20 years.

The William Lanford House with its 3 early 20th century barns maintains a high degree of architectural integrity. The house illustrates how Alabama's residential architecture evolved from the Federal style to the Greek Revival style in the early nineteenth century. The barns are good, intact representations of early 20th century agricultural outbuildings.

HISTORICAL SUMMARY

William Lanford was born in 1797 in Spattsylvania County, Virginia and spent his boyhood in this county. He was the son of Robert Lanford, one of the earliest land speculators in Huntsville. In 1843, William purchased 1,975 acres from James W. Camp. He built the present mansion on this property.

William Lanford contracted with William C. Leadingham in 1850 to build the house. The house was to be "52 by 36 feet, with as many doors and windows as Mr. Lanford may choose to have, also stairways, the house two stories high with a basement story of brick." The contract further stipulated that the house was to have two porticoes and the windows were to have blinds. The nouse, when completed in the summer of 1851, would have a central hall plan and eight rooms (1).

Although no formal archaeological survey has been made of this property, the potential for subsurface remains are high. Plantations of this type were sited within a constellation of

۰.

.

NPS Form 10-900-a (8-86)

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

Section	8	Page	_7_	Lanford, William, House
		_		name of property
				Madison County, Alabama
				county and State

dependencies and areas of high activity such as kitchens, privies, wells, tenant houses and other outbuildings. Buried portions may contain significant information that could be important to interpreting the entire property.

ENDNOTES

(1) Pat Jones, paper written in 1933.

NPS Form 10-900-a (8-86)	OMB No. 1024-0018						
Jnited States Department of the Interior National Park Service							
NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET							
Section 9 Page 8	Lanford, William, House name of property Madison County, Alabama						
county and State							
(1) Prepared by Harvie P. Jones, FAIA, Huntsv	Prepared by Harvie P. Jones, FAIA, Huntsville, AL.						
(2) Robert Donnell House: Annotated photograph	Robert Donnell House: Annotated photograph, Vol. #8, Harvie P. Jones; FAIA Historical						

. .

- (3) Hurn-Thach House, Annotated photograph, Vol. #40, Harvie P. Jones; FAIA Historical Photograph Collection, Huntsville, AL.
- (4) The Beauties of Modern Architecture, Minard Lafever, 1838.
- (5) Harvie P. Jones and Diane Simpson.

Photograph Collection, Huntsville, AL.

- (6) Diane Simpson.
- (7) Pat Jones

NPS Form 10-900-a (8-86)

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

Section <u>10</u> Page <u>9</u>	Lanford, William, House
	name of property
	Madison County, Alabama
	county and State

VERBAL BOUNDARY DESCRIPTION

All that part of the Southwest Quarter of Section 1 and all that part of the Southeast Quarter of Section 2, Township 4 South, Range 2 West, Madison County, AL, beginning at a point on the North margin of Madison Pike, said point is more particularly described as beginning North 1 degree 18 minutes East 42.0 feet and South 88 degrees 27 minutes East 846.44 feet from the Southwest corner of said Section 1, Township 4 South, Range 2 West, thence from the place of beginning North 88 degrees 27 minutes West 1,505.50 feet to a point in the center line of Indian Creek; thence along the center line of said Indian Creek as follows: North 0 degrees 36 minutes East 158.90 feet, North 10 degrees 48 minutes West 201.50 feet, North 18 degrees 45 minutes West 197.80 feet, North 76 degrees 21 minutes West 100.0 feet, South 80 degrees 19 minutes West 88.80 feet, North 60 degrees 54 minutes West 97.73 feet, North 20 degrees 07 minutes West 146.50 feet, North 3 degrees 13 minutes West 147.92 feet, North 32 degrees 21 minutes East 380.0 feet, North 3 degrees 10 minutes East 201.40 feet, North 55 degrees 05 minutes West 89.0 feet, North 2 degrees 30 minutes West 400.0 feet, North 3 degrees 07 minutes East 124.0 feet, North 23 degrees 04 minutes West 185.10 feet, North 19 degrees 47 minutes East 222.35 feet, North 33 degrees 10 minutes East 100.0 feet, North 7 degrees 31 minutes West 110.80 feet, and North 35 degrees 37 minutes West 205.91 feet to a point on the half Section line of said Section 2, thence South 89 degrees 20 minutes East along the half Section line of said Section 2, 1,101.10 feet to the center of the West boundary of said Section 1 and the East boundary of said Section 2, then South 89 degrees 03 minutes East along the half Section line of said Section 1, 845.40 feet to a point, thence South 1 degree 18 minutes East 34.84 feet to the place of beginning and containing 112.03 acres more or less.

BOUNDARY JUSTIFICATION

These are the boundaries currently associated with the property.

OMB No. 1024-0018

٩,

NPS Form 10-900-a (8 - 86)

United States Department of the Interior National Park Service

NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

Section	Photos	Page	10	Lanford, William, House
		-		name of property
				Madison County, Alabama
				county and State

The following information is the same for <u>all</u> the photographs:

- 1. William Lanford House
- 2. Huntsville, Madison County, Alabama

The following information applies to Photographs 1 and 2 (historic photographs):

- 3. Unknown
- 4. Unknown
- 5. Unknown

The following information applies to Photographs 3 through 20:

- 3. Harvie P. Jones, FAIA
- 4. June, 1993
- 5. Harvie P. Jones Photographic Collection


Photo 1: Aerial photo of William Lanford House property

Photo 2: C. 1950 view of front facade Camera facing north

- Photo 3: Front facade Camera facing north
- Photo 4: Front portico with repairs in progress Camera facing northeast
- Photo 5: Rear elevation Camera facing south
- Photo 6: East (side) elevation and rear elevation Camera facing southwest


NPS Form 10-900-a (8-86)	OMB No. 1024-0018						
United States Department of the Interior National Park Service							
NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET							
Section Photos Page 11_	Lanford, William, House name of property Madison County, Alabama county and State						
Photo 7: Outbuildings in rear yard Camera facing north							
Photo 8: 3 barns Camera facing northwest							
Photo 9: Raised floor storage cribs at the ce Camera facing north	entral side-hall barn						
Photo 10: Hay manger at the west barn Camera facing north							
Photo 11: Front door, first floor hall Camera facing south							
Photo 12: Rear door, first floor hall Camera facing north							
Photo 13: Dining room Camera facing east							
Photo 14: Parlor Camera facing west							
Photo 15: Dining room mantel Camera facing east							
Photo 16: Rear original service stair Camera facing northeast							
Photo 17: Enclosed rear verandah Camera facing west							
Photo 18: Door, second floor stair hall Camera facing west							
Photo 19: Southwest chamber, second floor Camera facing west							
Photo 20: Rimlock, northwest chamber, second f Camera facing south	loor						






HERVIE P. JONES, F.A.I.A., DEL.

= Photograph Number Direction of Camera



CIRCA 1850 WILLIAM LONFORD HOUSE SECOND FLOOR PLAN 1"=16 APPROX 7400 OLD MADISON PIKE HUNTSVILLE, MADISON COUNTY, ALDEDINA 5 JULY 1993

HORVIE P. JOHES, F.A.I.A., DEL.



HOLVIE P. JONES, FAIA, DEL.

