1. Name of Resource: Carpenter House 2. Original Owner: Calvin Carpenter

3. Other Names: Shouse School 4. Prehistoric Site

6. Owner's Name:

7. Owner's Address:

9. Recognition & Date:

10. N.R.Status & Date:

Thematic Name: 12. Historical Theme:

11. N.R.Group:

14. History:

owner.

5. Location:

Resource # 169

KENTUCKY HISTORIC RESOURCES								
Individual Inventory Form								

individual inv	Ventory Form Shelby Co	_ County	
. Name of Resource:	16. Date:		
Carpenter House		7 ]	
Original Owner:		4 ]	
Calvin Carpenter	17. Style:	1	
. Other Names: Shouse School	Antebellum Vernacular [3	V ]	
. Prehistoric Site × Building Object	18. Architect/Builder:	<u>-</u>	
Historic Site Structure Other	Unknown		
Location: East side of KY 148, 1 mile south	19. No. of Stories: 2 [2	.0]	
of Clark Station	20. Original Floor Plan:	_	
		CP ]	
. Owner's Name:	21. Single Pile X Double Pile N.A.		
Mrs. Palah Conner		<u>x</u>	
Mrs. Ralph Conner [P]  Owner's Address:	Hipped, standing seam n Note Original 23. Structural Material:		
. Owner's Address:	_	w ]	
Rte. 1, Finchville, KY 40002	24. Exterior Material:	1	
Evaluation: National Register [ N ]		wj	
Recognition & Date:	25. Foundation Material:		
Nat.Landmark Local Landmark		s ]	
Nat.Register HABS/HAER	26. Major Alterations: None		
Highway Marker KY Inventory 8-15-80	Moved/Rebuilt Other		
KY Landmark Certificate	x Additions		
0. N.R.Status & Date:	27. Special Features:		
1. N.R.Group: District Name: [ ]	None 28. Outbuildings:		
Mult.Resource Area: Shelby County [ ]		NC ]	
Thematic Name:	Non contributing 1 I 29. Original Function:	.۷0 ]	
2. Historical Theme:	Residential/Domestic, single dwell [0]	11A 1	
Primary: Architecture [030]	30. Present Use:	1111 1	
Secondary: Education [100]	As above [ (	01A]	
Other: [ ]	31. Condition:		
3. Statement of Significance:	<u>Excellent</u> [	<u>E</u> ]	
This property is significant under criteria A & C	C <sup>32</sup> . Endangered: Yes	<u>.                                    </u>	
as a well-preserved example of the mid-19th	NO	<u>x</u>	
century (1840-65) frame, 2-story, center-	33. Attach Photos:		
passage, single-pile plan in Shelby County.	Roll: Photo Nos: No. of Slides:		
It is one of seven such houses identified from	13 26 - 33 1		
the period. The site is also of signifi-[A,C]	10 20 - 30		
4. History:			
House was built between 1843 and 1848 (a			
metal plate dated 1848 formerly in possession			
of owner). Calvin Carpenter (1811-1865) is			
<del>-</del>	<b>3</b>	4	
believed to be the original owner and is buried	<b>.</b>		
on the farm. House was owned by Lucinda			
Carpenter in 1882. During the late 19th cen-			
tury, Ben and Vassie Dale Rucker Shouse			
operated a well-known private school at this			
site. House was purchased in 1915 by John			
L. Tucker, whose daughter is the present			
owner.			

34. Prepared by: C. Worsham

April 1986

35.

Date:

New Survey

Organization: V, Shelby Co. Hist. Society

Resurvey

X

15. Source of historical information and/or contact person: History from owner, Ida Mae Tucker Conner; Frances Cottongim, Shelby Co. Hist. Society; 1882 Atlas of Henry and Shelby Counties; KY.

42.

# KENTUCKY HISTORIC RESOURCES Individual Inventory Form

Resource # 169

38.	UTM Point of Primary Building: Quadrant: Fisherville	<b>Zone</b> <u>16</u>	Easting 6 4 0 1 7 0	North 4 2 2 6	_	G.I.S. Mod. Coordi.Accuracy	[	]
41.	UTM Points of Boundary (for N. R	. eligibl	e sites only):					
	A. B.	-	I H	). E.		 		
	C	_	Ī			 		


43.

Site Plan (and boundary description and justification for N.R. sites): 44. Beginning at A, south 186' along a fence to B, thence west 420' along a fence and a line of trees to C, thence north 186' along the east side of KY 148 to D, thence east 420' along a fence to the point of origin. The boundaries were chosen to encompass the house and its domestic-related space as defined by fences and trees separating it from surrounding fields. Included are 3 sheds,

Total Acreage in Present Property: 48

Point A is located at the intersection of two fences in the northeasterncorner of the yard and is 215 feet northeast of the northeast corner of the dwelling's ell.


Although the boundaries incorporate several non-contributing buildings, these are of small scale and could not be excluded without disrupting the relationship between the house and its yard.



#### 45. Description and House Plan:

### Exterior:

2-story, 5-bay, frame, center-passage, singlepile plan, plain narrow weatherboards, 1-story center porch with square columns and heavy Greek entablature, flushboards under porch, wide ceiling boards, pilasters flank 4-panel door and are themselves flanked by painted glass sidelights, panelled aprons, transom also of painted glass, beaded watertable, coursed stone foundation, frieze board with molding which stops short at each end of principal (west) facade, 6/6 sash, ... early blinds, roof hipped where 2-story ell joins main section of house on south end, interior brick . 20% end chimney, exterior brick chimney on north gable end standing seam metal roof, 1-story porch along south side of ell, partially collapsed exterior brick chim- \(\psi\) ney on east end of ell, original 1-story porch along north side of ell has square columns with early



# 13. Statement of Significancd: (continued)

cance in the county as the site of the Shouse School, a late 19th century private school.

45. Description and House Plan: (continued)

Greek moldings, east bay of porch added (no floor), flushboards under porch.

# Interior:

4-panel doors, earred door and window surrounds, pilastered mantles, woodwork is grained.

## Outbuildings:

Included are 5 non-contributing outbuildings.

The nominated area includes one contributing and five non-contributing buildings.