



Photo 1

Robert Patton/John G. Carlisle
House, looking northwest from
Garrard Street.

Photo by Walter E. Langsam

January 1984

Patton/Carlisle House

1533 Garrard Street

Covington, Kenton County, Ky.



Photo 2
Front and north side, looking
southwest.

Photo by Walter E. Langsam
January 1984
Patton/Carlisle House
1533 Garrard Street
Covington, Kenton County, Ky.



Photo 3

Front entrance porch, ca. 1890,
looking southwest along facade.

Photo by Walter E. Langsam

January 1984

Patton/Carlisle House

1533 Garrard Street

Covington, Kenton County, Ky.



Photo 4

Detail of front steps,
probably dating from ca. 1855,
looking northwest.

Photo by Walter E. Langsam

January 1984

Patton/Carlisle House

1533 Garrard Street

Covington, Kenton County, Ky.



Photo 5

Original entrance door;
bevelled-glass transoms and
sidelights probably ca. 1890.

Photo by Walter E. Langsam
January 1984
Patton/Carlisle House
1533 Garrard Street
Covington, Kenton County, Ky.



Photo 6

Detail of original hoodmold over
window on east front.

Photo by Walter E. Langsam

January 1984

Patton/Carlisle House

1533 Garrard Street

Covington, Kenton County, Ky.



Photo 7.

Rear facade looking southeast
from Collins (formerly Thomas)
Street, showing end of front
block at left.

Photo by Walter E. Langsam
January 1984
Patton/Carlisle House
1533 Garrard Street
Covington, Kenton County, Ky.



Photo 8

View from southwest showing relationship of front (right) and rear (left) blocks, with cross-bar between; two-story

frame bathroom wing behind front block.

Photo by Walter E. Langsam

January 1984

Patton/Carlisle House

1533 Garrard Street

Covington, Kenton County, Ky.



Photo 9

Detail of first story of rear facade from southwest, showing partially bricked-up central entrance, remains of one-story

south porch at right.

Photo by Walter E. Langsam

January 1984

Patton/Carlisle House

1533 Garrard Street

Covington, Kenton County, Ky.



Photo 10

Detail of south side looking northeast, showing junction of rear block (left) with seam not aligned with original wall under

return of modillioned cornice; outline of former one-story south porch; edge of bathroom wing at right.

Photo by Walter E. Langsam
January 1984
Patton/Carlisle House
1533 Garrard Street
Covington, Kenton County, Ky.



Photo 11

North side of house looking southwest, showing part of two-story gallery on cross-bar -- between front and rear wings.

Photo by Walter E. Langsam
January 1984
Patton/Carlisle House
1533 Garrard Street
Covington, Kenton County, Ky.