



Gilman-Hayden House
1871 Main Street
East Hartford, CT. 1.

G.L. Porteus, photo, 12/82
Filed with Conn. Historical
Commission, Hartford, CT.

Exterior, main facade, east



Gilman-Hayden House 2.

1871 Main Street

East Hartford, CT.

G.L.Porteus, photo, 12/82

Filed with Conn. Historical
Commission, Hartford, CT.

Exterior, rear ell, north-
west view.



Gilman-Hayden House 3.

1871 Main Street

East Hartford, CT.

G.L. Porteus photo, 12/82

Filed with Conn. Historical
Commission, Hartford, CT.

Interior, southeast room


corner cupboard, northwest
view.



Gilman-Hayden House 4.
1871 Main Street
East Hartford, CT.

G.L.Porteus photo, 12/82
Filed with Conn. Historical
Commission, Hartford, CT.

Interior, fireplace in
northeast parlor, first
floor, northwest view.



Gilman-Hayden House 5.
1871 Main Street
East Hartford, CT.

G.L. Porteus photo, 12/82
Filed with Conn. Historical
Commission, Hartford, CT.

Interior, northwest room,
detail of fireplace, north-
east view.



Gilman-Hayden House 6.

1871 Main Street

East Hartford, CT.

G.L.Porteus photo 12/82

Filed with Conn. Historical
Commission, Hartford, CT.

Interior, southwest room
first floor, southeast view



Gilman Hayden House 7.

1871 Main Street

East Hartford, CT.

G.L.Porteus photo 12/82

Filed with Conn. Historical
Commission, Hartford, CT.

Exterior, barn behind house
northeast view