

Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (1 of 19): Front facade and northside of Strickland's store; photographer facing northwest.



facing northeast.

Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (2 of 19): Front facade and north side of Strickland's store; photographer



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (3 of 19): Rear of Strickland's store (Left), cotton gin building (center) and 1930's cotton warehouse (right); photographer facing southwest.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (4 of 19): Entrance to bank, Strickland's store; photographer facing west.



Photographer: James R. Lockhart

Negatives Filed: Georgia Department of
Natural Resources
Date: August, 1981
Description (5 of 19): Detail of bank alarm,
Strickland's store; photographer facing
west.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (6 of 19): Entrance to dry goods section, Strickland's store; photographer facing north.



Photographer: James R. Lockhart

Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (7 of 19: First floor interior of dry goods section, Strickland's store: photographer facing northeast.



Photographer: James R. Lockhart

Negatives Filed: Georgia Department of
Natural Resources
Date: August, 1981
Description (8 of 19): First floor interior
of grocery and dry goods sections, Strickland's store; photographer facing east



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (9 of 19): First floor office Strickland's store; photographer facing First floor office, northeast.



northwest.

Photographer: James R. Lockhart

Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (10 of 19): Vault in bank area, Strickland's store; photographer facing



Photographer: James R. Lockhart

Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (11 of 19): Second floor, Strickland's store; photographer facing south.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (12 of 19): Second floor of Strickland's store showing freight elevator; photographer facing southwest.



Photographer: James R. Lockhart

Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (13 of 19): Strickland's store (left), cotton warehouse (center) and mule barn (right); photographer facing northwest



Photographer: James R. Lockhart

Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (14 of 19): Mule barn; photographer facing northwest.



Photographer: James R. Lockhart
Negatives Filed: Georgia Department of
Natural Resources
Date: August, 1981

Date: August, 1981
Description (15 of 19): Railroad freight building (left) and Strickland's store (Right) photographer facing northwest.



Photographer: James R. Lockhart
Negatives Filed: Georgia Department of
Natural Resources
Date: August, 1981
Description (16 of 19): Pale 1

Date: August, 1981
Description (16 of 19): Pole barn (left)
and cotton gin building (right); photographer facing northwest.



Photographer: James R. Lockhart

Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (17 of 19): Early Strickland store building, now part of storage building; photographer facing south.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (18 of 19): Cotton warehouse #2 behind Strickland's store; photographer facing northwest.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: August, 1981 Description (19of 19): Blacksmith shop/ pump house/generating plant; photographer facing northwest.