



Butler, Roswell, House

Essex, Chittenden County, Vermont

Michael T. McQuillen

August, 1999

Negative filed at Vermont Division for Historic Preservation

Description: View looking west of Butler house and Route 15  
with Essex Town Center commercial complex in the background

Photograph # 1





Butler, Roswell, House

Essex, Chittenden County, Vermont

Michael T McQuillen

August, 1999

Negative Filed at Vermont Division for Historic Preservation

Description: 3/4 view looking northeast of Butler house  
with non-contributing garage

Photograph # 2





Butler, Roswell, House

Essex, Chittenden County, Vermont

Michael T. McQuillen

August, 1999

Negative filed at Vermont Division for Historic Preservation

Description: 3/4 view looking southwest of Butler house

Photograph # 3





Butler, Roswell, House

Essex, Chittenden County, Vermont

Michael T. McQuillen

August, 1999

Negative filed at Vermont Division for Historic Preservation

Description: Interior view looking west in the attic of the

Butler house of the timber framing with

wood pegging

Photograph # 4