



PROPERTY OF THE NATIONAL REGISTER

Name: Coleman House

Location: 422 Kings Highway, Dewes, Delaware

Photographer: Sue Fox

Date: September 1976

Location of Negative: Division of Historical
and Cultural Affairs

Description: facade (east side) of house

Photograph Number: 1 ✓ 11

NOV 11 1976

DOE APR 11 1977



Name: Coleman House

Location: 422 Kings Highway, Lewes, Delaware

Date: 1971

Photographer: John Purnell

Location of Negative: Division of Historical and
Cultural Affairs

Description: facade of house before it was painted
red and before the addition of the front
porch

Photograph Number: 2 *11*

PROPERTY OF THE NATIONAL REGISTER

NOV 11 1976

DOE **APR 11 1977**



Name: Coleman House

Location: 422 Kings Highway, Lewes, Delaware

Photographer: Joan Norton

Date: September 1976

Location of Negative: Division of Historical and
Cultural Affairs

Description: facade of house showing details of
dormers and box cornices

Photograph Number: 3 *711*

PROPERTY OF THE NATIONAL REGISTER
NOV 11 1976

JOE APR 11 1977



PROPERTY OF THE NATIONAL REGISTER

Name: Coleman House

Location: 422 Kings Highway, Lewes, Delaware

Photographer: Sue Fox

Date: September 1976

Location of Negative: Division of Historical and
Cultural Affairs

Description: Detail of box cornice of wing, dormer,
and shingles

Photograph Number: 4 of 11

NOV 11 1976

DOE APR 11 1977



Name: Coleman House

Location: 422 Kings Highway, Lewes, Delaware

Date: September 1976

Photographer: Joan Norton

Location of Negative: Division of Historical and
Cultural Affairs

Description: North end of wing

Photograph Number: 5 of 11

NOV 11 1976

PROPERTY OF THE NATIONAL REGISTER

00E APR 11 1977



Name: Coleman House

Location: 422 Kings Highway, Lewes, Delaware

Photographer: Joan Norton

Date: September 1976

Location of Negative: Division of Historical and
Cultural Affairs

Description: South or rear of house

Photograph Number: 6 of 11

PROPERTY OF THE NATIONAL REGISTER

NOV 11 1976

JOE APR 11 1977



Name: Coleman House

Location: 422 Kings Highway, Lewes, Delaware

Photographer: Joan Norton

Date: August 1976

Location of Negative: Division of Historical and
Cultural Affairs

Description: Chimney breast in parlor of main portion
of house

Photograph Number: 7 of 11

NOV 11 1976

PROPERTY OF THE NATIONAL REGISTER

APR 11 1977



Name: Coleman House

Location: 422 Kings Highway, Lewes, Delaware

Photographer: Joan Norton

Date: August 1976

Location of Negative: Division of Historical and
Cultural Affairs

Description: Stairway in main portion of house

Photograph Number: 8 *cf 11*

NOV 11 1976

DOE APR 11 1977



Name: Coleman House

Location: 422 Kings Highway, Lewes, Delaware

Photographer: Joan Norton

Date: August 1976


Location of Negative: Division of Historical
and Cultural Affairs

Description: Original flooring in second floor of
main portion of house

Photograph Number: 9 of 11

NOV 11 1976

DOE APR 11 1977



Name: Coleman House

Location: 422 Kings Highway, Lewes, Delaware

Date: September 1976

Photographer: Sue Fox

Location of Negative: Division of Historical and
Cultural Affairs

Description: Corner cabinet (built-in) located in
dining room of wing

Photograph Number: 10 *of 11*

NOV 11 1976

PROPERTY OF THE NATIONAL REGISTER

DE APR 11 1977



Name: Coleman House

Location: 422 Kings Highway, Lewes, Delaware

Date: September 1976

Photographer: Sue Fox

Location of Negative: Division of Historical and
Cultural Affairs

Description: Detail of corner fireplace in dining
room of wing

Photograph Number: 11 of 11

PROPERTY OF THE NATIONAL REGISTER

NOV 11 1976

DUB APR 11 1977