

Photo #1 - April 1979 Central Christian Church Short & Walnut Streets Lexington, Kentucky From Southeast toward northwest Stone portions 1894 Brick portions 1952 JUL 1 0 1979

photographer: James A. Ross 257 Lexington Avenue Lexington, Ky.



Photo #2 - CA 1920 Central Christian Church Short & Walnut Streets Lexington, Kentucky

From Southwest toward northeast - Shows original sidewalk pattern and open vestibules JUL 1 0 1979

SEP | 1979 257 Lexington Avenue Lexington, Ky. TAYEHE CO.

photographer:

James A. Ross



Photo #3 - CA 1898

Central Christian Church
Short & Walnut Streets
Lexington, Kentucky

Shows original height of corner columns and original tracery in "transepts". Everything in picture (earliest known) is original.

phôtographer: James A. Ross

257 Lexington Ave.

Lexington. Kv

SEP 1 1 1979

FAYEHE



Photo #4 - April 1979

Central Christian Church Short & Walnut Streets Lexington, Kentucky

view from south to north JUL 1 0 1979 photographer:
James A. Ross
257 Lexington Avenue
Lexington, Ky. SEP | 1979

TAYCHE COUNTY



Photo #5

Central Christian Church Short & Walnut Streets Lexington, Kentucky

View from south to north. (Short Street elevation of 1894 structure) photographer: SEP 1 1 1979 James A. Ross 257 Lexington Avenue

Lexington, Ky.

FAVEHE (



Photo #6 - CA 1950 Central Christian Church Short & Walnut Streets Lexington, Kentucky Interior as modified in 1934 - no modifications have been made to date except adding choir screen and decorations. 101 10 1979

photographer:
James A. Ross
257 Lexington Avenue P | 1 1979
Lexington, Ky.

FAYEHE COUNTY



Photo #7 - April 1979 Central Christian Church Short & Walnut Streets Lexington, Kentucky View of cloister walk & garden from within. from northeast to south west. Chapel is to rear of photographer.

JUL 1 0 1979

photographer: James A. Ross SEP | 1 1979 257 Lexington Ave. Lexington, Ky.



Photo #8 - April 1979 Central Christian Church Short & Walnut Streets Lexington, Kentucky / Fermination of Cloister walk at east side of chapel - note wrought iron filigree screens. JUL 1 0 1979

photographer:
James A. Ross
257 Lexington Avenue
Lexington, Ky.



Photo # 9 - April 1979 Central Christian Church Short & Walnut Streets Lexington, Kentucky Street elevation from northwest toward southeast; shows relationship to major contemporary buildings in the city.

photographer: JUL 1 0 1979

James A. Ross
257 Lexington Avenue
Lexington, Ky. SEP | 1979



Photo #10 - Date unknown

Central Christian Church Short & Walnut Streets Lexington, Kentucky FALEHE COUNT original meeting house on Short Street - used CA 1816. photographer: SEP | 1979 James A. Ross 257 Lexington Avenue Lexington, Ky.

JUL 1 0 1979