

Location: 160 Fayette St., Morgantown, WV

Photo Credit: Mary Markey

Negative Filed At; Dept. of History, WVU

Description of Photo:
Main facade, west facade, and building's surroundings.

Direction of Photo: Southeast



Location: 160 Fayette St., Morgantown, WV

Photo Credit: Mary Markey

Negative Filed At: Dept. of History, WVU

Description of photo:

Auditorium, showing folding doors at rear for expanding the space, and the balcony which has been enclosed to create a storage room.

Direction of Photo: Northwest



Location: 160 Fayette St., Morgantown, WV

Photo Credit: Mary Markey

Negative Filed At: Dept. of History, WVU

Description of Photo:
First-floor auditorim and stage.

Direction of Photo: South



Location: 160 Eayette St. , Morgantown, WV

Photo Credit: Mary Markey

Negative Filed At: Dept. of History, WVU

Description of Photo:
Main entrance hall, looking toward street.

Direction of photo: north



Location: 160 Fayette St., Morgantown, WV

Photo Credit: Mary Markey

Negative Filed At: Dept. of History, WVU

Description of Photo:
Main entrance hall, looking toward auditorium.

Direction of Photo: South



Location: 160 Fayette St., Morgantown, WV

Photo Credit: Mary Markey

Negative Filed At: Dept. of History, WVU

Description of Photo:
Interior of second-floor office, showing original woodwork. Now occupied by Main St. Morgantown.

Diretion of Photo: West



Property Name: WCTU Community Building Location; 160 Fayette St., Morgantown, WV

Photo Credit: Mary Markey

Negative Filed At: Dept. of History, WVU

Description of Photo:

The second-floor rest room, sshowing original furnishings.

Direction of Photo: Northwest



Location: 160 Fayette St., Morgantown, WV

Photo Credit; Mary Markey

Negative Filed At: Dept. of History, WVU

Description of Photo:
Second-floor rest room, showing
original furnishings.

Direction of photo: southwest



Location: 160 Fayette St., Morgantown, WV

Photo Credit: Mary Markey

Negative Filed At : Dept. of History, WVU

Description of Photo:
Light fixture in rest room. Similar fixtures throughout building.

Direction of Photo: Southwest



Location: 160 Fayette St., Morgantown, WV

Photo Credit: Mary Markey

Negative Filed At: Dept. of History, WVU

Description of Photo:
Second-floor hallway and office entrance with mailbox for occupants.

Direction of Photo; Southwest



Location: 160 Fayette St., Morgantown, WV

Photo Credit: Mary Markey

Negative Filed At: Dept. of History, WVU

Description of Photo:

Gymnasium and mezzanine with exercise equipment, located in basement.

Direction of Photo: Northeast