



Threlkeld/Weakley House, Benson Pike,
Shelby Co., Kentucky HABS
Mary Oppel Nov. 1980
Photo. 1. Southeast corner.



Threlkeld/^WWeakley House, Benson Pike.

Shelby Co., Kentucky HABS

Mary Oppel Nov. 1980

Photo. 2. View from northwest.



Threlkeld/Weakley House, Benson Pike,
Shelby Co., Kentucky HABS
Mary Oppel Nov. 1980
Photo. 3. South wall frame section.



Threlkeld/Weakley House, Benson Pike,
Shelby Co., Kentucky March 1981
Gibson Worsham HABS

Photo. 4. Interior west room frame
section looking toward southwest corner
showing arch brace in west end wall over
door.



Threlkeld/Weakley House, Benson Pike,
Shelby Co., Kentucky HABS

Gibson Worsham Nov. 1980

Photo. 5. South wall stone section.



Threlkeld/Weakley House, Benson Pike,

Shelby Co., Kentucky HABS

Gibson Worsham Nov. 1980

Photo. 6. West wall stone section.



Threlkeld/Weakley House, Benson Pike,
Shelby Co., Kentucky HABS

Mary Oppel Nov. 1980

Photo. 7. South corner, east wall,
frame section, mud infill exposed.



Threlkeld/Weakley House, Benson Pike,
Shelby Co., Kentucky HABS
Gibson Worsham March 1981

Photo. 8. Interior, east room, frame
section looking toward southeast corner.



Threlkeld/Weakley House, Benson Pike
Shelby Co., Kentucky HABS

Gibson Worsham March 1981

Photo. 9. Mantel in stone section.



Threlkeld/Weakley House, Benson Pike,
Shelby County, Kentucky

Gibson Worsham

March 1981

HABS

Photo. 10. Corbelled stone springhouse