



Cornelius Jensen Ranch
later structures
Rubidoux, Riverside, County
California

Jensen, Cornelius⁵ House

Stephen Becker, Photographer
7/20/1979

Negative filed at
Riverside County Parks
Department SEP 6 1979

1 of 5. View to the south-
east of board-and-batten
residential structure with
shed addition at left.

8-2-79



Cornelius Jensen Ranch
later structures
Rubidoux, Riverside, County
California
Stephen Becker, Photographer

Jensen, Cornelius⁶, House

7/20/1979 Negative filed at
Riverside County Parks
Department

SEP 6 1979

2 of 5. View to the north
northwest from near the
Jensen Ranch complex show-
ing the board-and-batten
house built in the 1930s.

8-2-79



Cornelius Jensen Ranch
Later structures
Rubidoux, Riverside, County
California

SEP 6 1979

Jensen, Cornelius, House

Stephen Becker, Photographer
7/20/1979

Negative filed at
Riverside County Parks
Department

3 of 5. View to the south-
east showing the open shed;
Jensen Ranch complex is in
the background at the right.

8-2-79



Cornelius Jensen Ranch
Water structures
Rubidoux, Riverside, County
California

SEP 6 1979

Jensen, Cornelius, House

Stephen Becker, Photographer
7/20/1979
Negative filed at
Riverside County Parks
Department

4 of 5. View to the north-
west of the well house
near the board-and-batten
residence.

8-2-79



Cornelius Jensen Ranch
later structures
Rubidoux, Riverside, County
California

SEP 6 1979

Jensen, Cornelius, House

Stephen Becker, Photographer
7/20/1979

Negative filed at
Riverside County Parks
Department

5 of 5. View to the south-
west of the concrete reser-
voir (mistakenly marked on
USGS maps as a structure.

8-2-79



Jensen, Cornelius House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks
Department.

SEP 6 1979

1 of 12. View to the south
main residential structure
(left) and small winery
(right center), and large
winery (behind trees, far
right).

AUG 2 1979



Jensen, Cornelius, House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks
Department.

SEP 6 1979

2 of 12. View to the south-
west. Front side of main
residence (porch was
located on this facade).

AUG 2 1979



Jensen, Cornelius^o, House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks
Department.

SEP 6 1979

3 of 12. View to the north-
east. Rear of small winery
(left to left center) and
milk house (right).

AUG 2 1979



Jensen, Cornelius House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks
Department.

SEP 6 1979

4 of 12. View to the north-
west. Gable end of resi-
dence (right to right
center), pump house, milk
house and tank house (right
to left).

AUG 2 1979



Jensen, Cornelius, House
Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative Filed at
Riverside County Parks
Department

SEP 6 1979

5 of 12. View to the south-
east (from inside the com-
plex of Ranch structures).
Left to right: tank house,
wash house (behind, par-
tially obscured) and chicken
coop.

AUG 2 1979



Jensen, Cornelius House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks
Department.

SEP 6 1979

6 of 12. View to the east
showing pump house and
southern corner of
residence.

AUG 2 1979



Jensen, Cornelius, House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks
Department.

SEP 6 1979

7 of 12. View to the south-
west of the large winery
(this wall is directly
across from and parallels
the back walls of the
residence and the small
winery).

AUG 2 1979



Jensen, Cornelius, House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks
Department.

SEP 6 1979

8 of 12. View to the north-
west of a side wall of the
large winery. Residence,
milk house and small winery.
are to the right, off
frame.

AUG 2 1979



Jensen, Cornelius, House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks
Department.

SEP 6 1979

9 of 12. View to the north-
east from the main entrance
to the residence. Property
boundary is at the second
fence line (mid frame).

AUG 2 1979



Jensen, Cornelius, House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks
Department.

SEP 6 1979

10 of 12. View to the south-
east from the southeastern
gable end of the residence.
Property boundary is beyond
second fence line.

AUG 2 1979



Jensen, Cornelius, House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA

Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks
Department.

SEP 6 1979

11 of 12. View to the south-
west from the southwestern
side of the large winery.
Property boundary is at the
second fence line.

AUG 2 1979



Jensen, Cornelius, House

Cornelius Jensen Ranch
Rubidoux, Riverside County, CA
Paul Romero, Photographer

5/24/1979 Negative filed at
Riverside County Parks De-
partment.

SEP 6 1979

12 of 12. View to the north-
west from a point between
the large winery and small
winery. Property boundary
is just beyond the slight
rise near the utility
poles.

AUG 2 1979