

NOV 14 1978

Mary Cronan Oppel Kentucky Heritage Commission December 1977

MAY 3 0 1978

Photo 1: Photo taken from the northeast showing the facade and north side.




NOV 1 4 1978

Mary Cronan Oppel Kentucky Heritage Commission December 1977

MAY 30 1978

Photo 2: Detail of the front entrance taken from the east.



May 1 4 1978

Mary Cronan Oppel Kentucky Heritage Commission December 1977

MAY 3 0 1978

Photo 3: Photo taken from the southeast. Notice how the ell adjoins the main block.



1 4 1978

Mary Cronan Oppel
Kentucky Heritage Commission
December 1977
MAY 3 0 1978

Photo 4: Photo taken from the west showing the rear of the house. Notice the slope of the roof on the left



11 1978

Mary Cronan Oppel Kentucky Heritage Commission Cecember 1977

MAY 3 0 1978

Photo 5: Interior photo showing the staircase in the entrance hall. Notice the molding around the door to the extreme right.



MUV 1 4 1978

Mary Cronan Oppel Kentucky Heritage Commission December 1977

MAY 3 0 1978

Photo 6: Interior photo showing the trim around the front entrance.



NOV 1 4 1978

Mary Cronan Oppel Kentucky Heritage Commission December 1977 MAY 30 1978

Photo 7: Interior photo of the wainscoting in the north parlor.



NOV 1 4 1978

Mary Cronan Oppel Kentucky Heritage Commission December 1977

MAY 30 1978

Photo 8: Interior photo showing the detail of the north parlor mantel.



NOV 14 1978

Mary Cronan Oppel Kentucky Heritage Commission December 1977

MAY 3 0 1978

Photo 9: Interior photo of one of the cupboards which flank the mantel in the north parlor.



NOV 14 1978

Mary Cronan Oppel Kentucky Heritage Commission December 1977

MAY 30 1079

Photo 10:

Interior photo showing the detail of the south parlor mantel.



Mary Cronan Oppel
Kentucky Heritage Commission
December 1977
MAY 3 0 1978

NOV 1 4 1978

Photo 11: Interior photo showing the cupboard and door trim in the south parlor.



Mary Cronan Oppel Kentucky Heritage Commission December 1977

MAY 3 0 1978

Photo 12:

Interior photo showing the cupboard in the dining room.

NOV 1 4 1978



NOV 1 4 1978

Mary Cronan Oppel Kentucky Heritage Commission December 1977

MAY 3 0 1978

Photo 13:

Interior photo of the original kitchen fireplace and hearth.



Mary Cronan Oppel Kentucky Heritage Cómmission December 1977

MAY 3 0 1978

Photo 14:

Interior photo of the mantel and cupboards in the north rear room.

NOV 1 4 1978