

Clemmer Theater - the Met 6/1/88

 $\frac{\text{\#1 of 10}}{\text{ing exterior (east and north elevations)}}$.

West 901 Sprague Ave. Spokane, Washington

Photo: Fred Hilker 509 326 7561




Clemmer Theater - the Met 6/1/88

#2 of 10 - Looking southeast at the building exterior (north elevation). Davenport Hotel (NRHP '76) in the background.

West 901 Sprague Ave. Spokane, Washington


Photo: Fred Hilker 509.326,7561



Jerry Prout Photographer 509-327-9643

Clemmer Therter - the Met 6/1/88

#3 of 10 - Exterior brickwork and terra cotta detailing at mezzanine level cornice.



Jerry Prout Photographer 509-327-9643 ©

Clemmer Theater - the Met 6/1/88

#4 of 10 - Looking up at the rotunda dome at the entry lobby



Jerry Prout Photographer 509-327-9643 ©

Clemmer Theater - the Met 6/1/88


#5 of 10 - Looking south from the entry lobby with the rotunda dome above to the ramp leading up to the balcony seating



Jerry Prout Photographer 509-327-9643 ©

Clemmer Theater - the Met 6/1/88

#6 of 10 - Looking south from the ramp to the lobby colonade. The light fixtures are not original.



Jerry Prout Photographer 500.327 9643 ©

Clemmer Theater - The Met 6/1/88

#7 of 10 - Looking west from the upper balcony area to the stage and proscenium arch. Note the arched colonade flanking the stage; the coffered proscenium vault (an architectural first); and the landscape murals - all original.



Jerry Prout Photographer 509-327-9643 ©

Clemmer Theater - the Met 6/1/88

#8 of 10 - Looking south from the balcony to the arched colonade and cornice, the coffered proscenium vault, original landscape murals, and barrel vaults over the balcony seating. All light fixtures are original.



Band & 88

Jerry Prout Photographer 509-327-9643

Clemmer Theater - the Met 6/1/88

#9 of 10 - Looking north from the balcony to the arched colonade and cornice, the coffered proscenium vault, original landscape murals, and barrel vaults over the balcony seating. All light fixtures are original.



Marry Prout Photographer 509-327-9643 €

Clemmer Theater - the Met 6/1/88

 $\underline{10~\text{of}~10}$ - Detail of the arched colonade and decorative cornice with the proscenium vault above.




Chemmer Theater Spokano Spokano Co., WA Photo Fred Hilker, June, 1988 Neg. OAHP east ord north

10/10


Phito #



Clemmer Theater Spokane, Spokane W, WA Photo: Fred Hilker, June, 1988 Neg: OAHP View Looking SE A+ North elevation Pho 6 + 2 of 10



Clemmer Theoter Spokane, Spokane Go, WA Thata: Jerry Prout, June, 1988 Neg: OAHP View detail exerior brickwark That # 3 of 10



Clemmer Theaker Spokano, Spokano Co, with Photo: Jerry Prout, gine, 1988 Neg OAHP Looking up at rotunda Photo # 4 of 10



Clemmer theater Spokane, Spokane, uA, Meg: OAHP SAITH FIRM PM view. Looking south from entry Number 5 of 10



Clemmer Theater
Spokone, Spokone Co, wt
Shoto: Jerry Prout, 6/88
Neg OAHP View: looking south toward lobby # 6 of 10



Clemmer Theorem Spokane, Spokane G., WH Photo: Jerry Prost, gine, 1988 Neg: OAHP View: Looking west from
upper ballony
Photo # : 7 of 10



Chemmer theater Spokane, Spokane Co., wat Spokane, Spokane Co., wat photo: Jerry Prout, June, 1988 Neg: OAHP View: Looking south from bolomy.

Photo # 8 of 10



Clemmer Theoder Spokans, Spokane G, UA Photo: Jerry Prout, June, 1988 Neg: OAHD View. Looking N from Bollmy. Photo # 9 of 10



Clemmer Theater Spokane, Spokane Co, wA
photo Jerry Prout, June, 1988
Reg: OATH View Detail of colonade and cornice in theater Photo: # 10 0/10