


UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE <i>(Assigned by NPS)</i>
Croke-Patterson-Campbell House	Same	SEP 19 1973
2. LOCATION		
STATE	COUNTY	TOWN
Colorado	Denver	Denver
STREET AND NUMBER		
428-430 East 11th Avenue		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
State Historical Society of Colorado	3-15-73	State Historical Society
4. IDENTIFICATION		
DESCRIBE VIEW, DIRECTION, ETC.		



Taken of the North facade, showing tower and spires, with a glimpse of the carriage house to the far right of the photograph.

1 of 2 photos




UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE <i>(Assigned by NPS)</i>
Croke-Patterson-Campbell House	Same	SEP 19 1973
2. LOCATION		
STATE	COUNTY	TOWN
Colorado	Denver	Denver
STREET AND NUMBER		
428-430 East Eleventh Avenue		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
State Historical Society of Colorado	3-15-73	State Historical Society
4. IDENTIFICATION		
DESCRIBE VIEW, DIRECTION, ETC.		



Taken of the east and north facades from a viewpoint looking west. Shows stairs and porches of both facades as well as the entire north facade of the carriage house.

2 of 2 photos