



Crandell, Prudence House

Lanterbury, Windham County, CT

Courtesy of Prudence Crandall Museum



PRUDENCE CRANDALL HOUSE

Canterbury, Connecticut

East Facade

Photo by Dennis Oparowski, September 1989



PRUDENCE CRANDALL HOUSE

Canterbury, Connecticut

Northwest view

Photo by Dennis Oparowski, September 1989



PRUDENCE CRANDALL HOUSE
Canterbury, Connecticut
Front Hallway, looking west
Photo by Dennis Oparowski, September 1989



PRUDENCE CRANDALL HOUSE

Canterbury, Connecticut

Front entry from rear of house

Photo by Dennis Oparowski, September 1989




PRUDENCE CRANDALL HOUSE
Canterbury, Connecticut
Front hall/staircase

Photo by Dennis Oparowski, September 1989



PRUDENCE CRANDALL HOUSE
Canterbury, Connecticut
Northeast Parlor, first floor
Photo by Dennis Oparowski, September 1989




Prudence Crandall House
Canterbury, Connecticut
Dennis Oparowski

September 10, 1989

Prudence Crandall Museum
Detail - Front Hallway Ceiling
Cornice Moulding.

25/89



Prudence Crandall House
Canterbury, Connecticut

Dennis Oparowski

September 10, 1989

Prudence Crandall Museum
Detail, staircase



Prudence Crandall House
Canterbury, Connecticut

Dennis Oparowski

September 10, 1989

Prudence Crandall Museum

East View, Main Entry



Prudence Crandall House
Canterbury, Connecticut

Dennis Opárowski

September 10, 1989

Prudence Crandall Museum

View - North East, Attic