



Gunter-Summers House

Lexington County, S. C.

Karen Nickless, Jan. 20, 1987

2329 Lincoln St.

Columbia, S. C.

Facade (North elevation)



Gunter-Summers House

Lexington County, S. C.

Sherry Piland, June 1987

S. C. Dept. of Archives & History

Columbia, S. C.

Oblique view of facade (N elev.)
and east elevation at left



Gunter-Summers House

Lexington County, S. C.

Karen Nickless, Jan. 20, 1987

2329 Lincoln St.

Columbia, S. C.

Oblique view from southeast



Gunter-Summers House

Lexington County, S. C.

Karen Nickless, Jan. 20, 1987

2329 Lincoln St.

Columbia, S. C.

Detail of trim, North elevation



Gunter-Summers House

Lexington County, S. C.

Karen Nickless, Jan. 20, 1987

2329 Lincoln St.

Columbia, S. C.

Wainscoting, NW room on first
floor



Gunter-Summers House
Lexington County, S. C.
Karen Nickless, Jan. 20, 1987
2329 Lincoln St.
Columbia, S. C.
Oblique view of property from
southeast



Gunter-Summers House
Lexington County, S. C.

Karen Nickless, Jan. 20, 1987

2329 Lincoln St.

Columbia, S. C.

Barn, west elevation



Gunter-Summers House

Lexington County, S. C.

Karen Nickless, Jan. 20, 1987

2329 Lincoln St.

Columbia, S. C.

Barn, north elevation



Gunter-Summers House

Lexington County, S. C.

Karen Nickless, Jan. 20, 1987

2329 Lincoln St.

Columbia, S. C.

Smokehouse, oblique view from
northwest