



Ditch Rider House


August 1997

Interior Photo #1

CHRISTIE SLAPPER

Photo #1

006 +00+00+00-04



View of front door inside of the
screen porch






Ditch Rider House, AUGUST 1997

INTERIOR PHOTO # 2

CHRISTIE Pappay, PHOTOGRAPHER



Ceiling detail shows extent of water damage to plaster and shows paint peeling back to reveal original paint


CONFIRMATION

10-00+00+00+ 120K5



Ditch rider House

August






INTERIOR

PHOTO # 3

CHRISTIE SLAPPEY,

PHOTO GRADER



^ SHOWS the closet
THAT WAS added to
(BED ROOM) "

SW DOOR



3599 < 5 > 020 + 00 + 00 + 00 - 02 PHOTO 1




DITCH RIDER House, August 1997



INTERIOR PHOTO #4

CHRISTIE SLAPPY - PHOTOGRAPHER



43599 < 4>021 +00+00+00-02 ET PHOTO

BATHROOM ADDITION - SHOWS PIPE
FOR SINK, TOILET, AND EXISTING TUB.





Ditch House, August 10.

INTERIOR PHOTO # 5

CHRISTIE SUPER PHOTOGRAPHER

3599< 6>018 +00+00+00-03
ET-PHOTO

A VIEW OF HEATING SYSTEM IN
SE Room, ALSO SHOWS BEAD-BOARD.



D. Schriener Hall August 1997

INTERIOR photo

CHRISTOPHER SLAPPEY, PHOTOGRAPH

Kodak SAFETY FILM

7>016 +00+00+00-05


TO



NORTH VIEW OF KITCHEN

SHOWS ORIGINAL FLOOR

UNDER DETEIORATED LINOLEUM!





DICKENS HOUSE August 10

INTERIOR PHOTO

Christy Happey, Photographer

8>014 +00+00+00-01

SHOWS STOVE PIPE OUTLET AND
BUILT-IN PANTRY BOTH
APPEAR TO BE ORIGINAL



Ditch House, August 1997

Interior photo

CHRISTY SLAPPY, PHOTOGRAPHER

10-00+00+00+ 210<6

"View of ORIGINAL CABINETRY
IN KITCHEN"



DITCH HOUSE

AUGUST 1997

INTEREST PHOTO

CHRISTIC SLAPPEY

grapher



PHOTO 1997 2>026 +00+00+00-01

"View of ghost of AREA"





Dinner House August 1997

Interior Photo # 10

CHRISTIE SLAPPY, PHOTOGRAPHER

>028 +00+00+00-02

View OF CABINETRY IN Kitchen






Diner House,

August 1951



INTERIOR VIEWS # 11

CHRISTIE



PHOTOGRAPHER



SHOWS ORIGINAL 5

doors"

9004+00+00+00-03



43601 > 9004+00+00+00-03 JET PHOTO



Dick Rider House August 1997

Interior View #1

CHRISTIE SLAPPEY PHOTOGRAPHER



10+00+00+00+00+00

11 View of NW Room (Bedroom)


SHOWS ghost covered

doorway






Ditch rider House





1997

INTERIOR PHOTO

SLAPPEY PHOTOGRAPHER



SHOWS TEMPERA LIKE PAINT CONCENTRATION (THE LIGHT
COLOR DOWN A PICTURE RACE LEVEL AND
DARK UNDER MESH) REVEALED UNDER
PEELING LEAD BASED AND GREEN PAINT
ALSO SHOWS WATER DAMAGE CEILING





DICKRIDER HOUSE August 1997

INTERIOR PHOTO #14

CHRISTIE SLAPPEY PHOTOGRAPH

10-00+00+00-01

SHOWS BASE OF STAIRS AND FALLEN
PLASTER DAMAGED BY WATER






Ditch Rider House Aug 1997

INTERIOR PHOTO #15

CHRISTIE SLAUGHTER PHOTOGRAPHER

00+00+00-03

Photo of snake STAINED ceiling
and light fixture on BACK Porch





Ditch Rider House, Ave

INTERIOR PHOTO #16

CHRISTIE SLAPPEY, PHOTOGRAPHER



00+00+00+00-01



SHOWS ROOM FROM BACK PORCH
TO BASEMENT



Ditch Rider House August 1997

INTERIOR PHOTO

Christie Slappey, Photographer



Christie Slappey
Kodak PAPER

9< 12>006 +00+00+00-01
HOTO

View of Stairwell leading to
Basement. Shows signature

that reads "Fred Oxford August 7/41."






Ditch rider Henne August 1997

Extension photo #

CHRIST SLAPPY PHOTOGRAPHER



026 +00+00+00-05



View of Ditch rider House from
SW corner of property, across

Hwy 1212"



Ditch Riden House August

EXTERIOR PHOTO 2

CHRISTIE SLAPPEY, PHOTOGRAPHER



027 +00+00+00-05

View of Ditch Riden House from

HW 4 212





Ditch Rider House

August

EXTENSION PHOTO

#

581

Chaotic Slappy

Photographer

3>023 +00+00+00-06

View of Ditch Rider House from
driveway approach



DitchRider House August 1997

Extension Photo

Chazelle Slappy, photographer

021 +00+00+00-04

View of MATURE Vegetation
Surrounding house



Ditcher House

August 1997

EXPOSED PHOTO # 5

CHRISTIE SLAPPEY, PHOTOGRAPHER

10>010 +00+00+00-04

"View of double WINDOWS

ALSO SHOWS EXPOSED PARTS"




Ditch ~~Wider~~ House

August 1997

Exterior photo # 6

CHRISTIE SLAPPY,



photographer

OTO < 5>019 +00+00+00-06

"EASTERN View of House"



Dick Rider House August 1997

EXTERIOR PHOTO # 7

CHRISTY SLAPPY, PHOTOGRAPHER

13004 +00+00+00-02
OTO

EASTERN VIEW OF BACK PORCH

SHOWS ELECTRICAL ELEMENTS,
CISTERN, AND ROOFING SYSTEM



DITCH RIDER HOUSE

AUGUST 1997

EXTERIOR PHOTO # 8

CHRISTIE SLAPPEY PHOTOGRAPHER

14>002 +00+00+00-03
OTO

"SHOWS CISTERN AND PUMP"






Ditch Rider House August 1957

EXTERIOR PHOTO # 9

CHRISTIE SLAPPEY, PHOTOGRAPHER

" SHOWS NORTHERN VIEW FROM HOUSE .
INCLUDES BARN "



OTO
< 14>002 +00+00+00-03



Ditch rider How August 1997

EXTERIOR PHOTO # 10-A

CHRISTIE Slappay, PHOTOGRAPHER

3>016 +00+00+00-03

" ~~Slappay~~ CONTRIBUTING STRUCTURE
THE ~~BAR~~, FROM FRONT VIEW "



Ditch Road House August 19


EXTENSION PHOTO # 10-B

CHRISTIE SLAPPEY, PHOTOGRAPHER

4>014 +00+00+00-02

OTO

" SHOWS INTERIOR OF BARN "





Ditch rider House

August 1997

EXTERIOR PHOTO # 11

CHRISTOPHER SHAPPEY, PHOTOGRAPHER

50012 +00+00+00-02

" Snow Sorenson Lateral
curving through the northern
end of property "



Ditch Rider House

Aug 1997

EXTERIOR PHOTO # 12

CHRISTIE SLAPPEN PHOTOGRAPHER

2018 +00+00+00-03

TO

SHOWS SORENSON LATERAL AND
EXISTING VEGETATION



Ditch Ridge House August 1997

EXTENSION PHOTO #13

CARISTIE SLAPPY, PHOTOGRAPHER

6>010 +00+00+00 02

" SHOWS SOREN SON
AND CULVERT "



DITCH RIDER HOUSE

August 1997

EXTERIOR PHOTO # 14

CHRISTOPHER SLAPPEY, PHOTOGRAPHER

98< 6>017 +00+00+00-06

PHOTO

SHOWS NORTHERN ELEVATION
OF HOUSE"



Ditch Rider House

August 1997

Exterior Photo # 16

CHRISTIE SLAPPEY, PHOTOGRAPHER

598< 7>015 +00+00+00-05
PHOTO

"Western elevation of house"



Dutch Rider House

Kodak August 1997

EXTERIOR PHOTO # 17

CHRISTIE SLAPPY, PHOTOGRAPHER

Kodak
08013 +00+00+00-05

SHOWS VEGETATION AROUND
STRUCTURE

Kodak
PAPER
Kodak



Ditch Rider House August 1997

EXTERIOR PHOTO # 18

CHRISTIE LARREY, PHOTOGRAPHER

< 11 > 007 + 00 + 00 + 00 - 04
OTO

" Shows Southern elevation "



Ditch Ride n House

Belle Fourche Irrigation Project

HIGHWAY 212 WEST OF NISLAND, BUTTE COUNTY,
SOUTH DAKOTA

PHOTO # 1 VIEW TO NORTH OF DITCH RIDER
HOUSE PROPERTY SETTING.
HIGHWAY 212 IN FOREGROUND.

NEGATIVE AT: U.S. - BUREAU OF RECLAMATION
515 - 9TH STREET # 101
RAPID CITY, SOUTH DAKOTA
57701

PHOTO BY: CHRISTY SLAPPY, U.S. BUREAU OF RECLAMATION

September 2000



Dirch rider House

Bene Fourche Irrigation Project

Highway 212 West of Nisland, Butte County,
South Dakota

Photo # 3 View of North and East
Elevations of House

RELATIVE AT: U.S. BUREAU OF RECLAMATION
515-9TH STREET #101
RAPID CITY, SOUTH DAKOTA 57701

PHOTO BY: CHRISTY SLAPPY, U.S. BUREAU OF
RECLAMATION

September 2000



Ditchman House

Belle Fourche Irrigation Project

Highway 212 West of Nisland, Butte County,
South Dakota

Photo #5 View of East Elevation of
House

NEGATIVE AT: U.S. Bureau of Reclamation
515 - 9th Street #101
Rapid City, South Dakota 57701

Photo by: Christy Slappy, U.S. Bureau of Reclamation
September 2000



Ditch Rider House

Belle Fourche Irrigation Project

Highway 212 west of Nisland, Butte County

SOUTH DAKOTA

PHOTO #9 VIEW OF BARN AND

DITCH RIDER HOUSE PROPERTY SETTING
TO NORTHEAST. MILLER BUTTE IN
BACKGROUND

NEGATIVE AT: US BUREAU OF RECLAMATION

515 - 9TH STREET #101

RAPID CITY, SOUTH DAKOTA 57701

PHOTO BY: CHRISY SLAPPEY, U.S. BUREAU OF RECLAMATION

SEPTEMBER 2000



DIX RIDER HOUSE

BELLE FOURCHE IRRIGATION PROJECT

HIGHWAY 212 WEST OF NISLAND, BUTTE COUNTY,
SOUTH DAKOTA

PHOTO # 10 VIEW OF SOUTH ELEVATION OF BARN

NEGATIVE AT U.S. BUREAU OF RECLAMATION
515 - 9TH STREET # 101
RAPID CITY, SOUTH DAKOTA 57701

PHOTO BY: CHRISTY SLAPPEY, U.S. BUREAU OF RECLAMATION

SEPTEMBER 2000



Ditch Rider House

Belle Fourche Irrigation Project

HIGHWAY 212 WEST OF HIGHLAND, BUTTE COUNTY,
SOUTH DAKOTA

PHOTO # 11 View TO WEST OF SORENSON LATERAL

NEGATIVE LOCATED AT: U.S. BUREAU OF RECLAMATION, 515 - 9TH STREET, 101
RAPID CITY, SOUTH DAKOTA 57701

PHOTOGRAPH BY: CHRISTY SLAPPEY, U.S. BUREAU OF RECLAMATION

SEPTEMBER 2000



DITCH RIDER HOUSE

BELLE FOURCHE IRRIGATION PROJECT
HIGHWAY 212 WEST OF NISLAND,
BUTTE COUNTY, SOUTH DAKOTA

PHOTO # 14 VIEW OF NORTH ELEVATION
OF HOUSE

NEGATIVE AT: U.S. BUREAU OF RECLAMATION
515 - 9TH STREET #101
RAPID CITY, SOUTH DAKOTA 57701

PHOTO BY: CHRISTY SLAPPEY, U.S. BUREAU OF RECLAMATION
SEPTEMBER 2000



Ditch Rider House

Belt Fourch IRRIGATION Project

Highway 212 WEST OF NISLAND, BUTTE COUNTY,
SOUTH DAKOTA

PHOTO # 15 VIEW TO NORTHEAST OF
DITCH RIDER HOUSE PROPERTY
SETTING. MILLER BUTTE
IN BACKGROUND.

NEGATIVE AT: U.S. BUREAU OF RECLAMATION
515 - 9TH STREET #101
RAPID CITY, SOUTH DAKOTA 57701

PHOTO BY: CHRISTY SLAPPEY, U.S. BUREAU OF RECLAMATION
September 2000



DITH RIDER House

BELLE FOURCHE IRRIGATION PROJECT, HIGHWAY 212, WEST OF NISLAND,
BUTTE COUNTY, SOUTH DAKOTA

PHOTO # 16

VIEW OF WEST ELEVATION
OF THE HOUSE

NEGATIVE AT: U.S. BUREAU OF RECLAMATION
515-9TH STREET # 101
RAPID CITY, SOUTH DAKOTA 57701

PHOTO BY: CHRISTY SLAPPEY, US BUREAU OF RECLAMATION

September 2000



Ditchrider House

BELLE FOURCHE IRRIGATION PROJECT, HIGHWAY 212, WEST OF NISLAND,
BUTTE COUNTY, SOUTH DAKOTA

PHOTO # 18 VIEW OF THE SOUTH ELEVATION OF
THE HOUSE. THIS IS THE FRONT
PORCH AND MAIN ENTRY.

NEGATIVE AT: US BUREAU OF RECLAMATION
515 - 9TH STREET # 101
RAPID CITY, SOUTH DAKOTA 57701

PHOTO BY CHRISTY SLAPPEN, U.S. BUREAU OF RECLAMATION

September 2000