

Gloria Mills Kentucky Heritage Commission Frankfort, Kentucky March 1978

JUL 7 1978

Photo 1.7 View from northwest showing facade of building complex.



Gloria Mills
Kentucky Heritage Commission
Frankfort, Kentucky
March 1978

Photo 2. View from west showing facade on central block.



Gloria Mills Kentucky Heritage Commission Frankfort, Kentucky March 1978 JUL 7 1978

Photo 3. View from northwest showing facade of Carnegie Library.



Gloria Mills Kentucky Heritage Commission Frankfort, Kentucky March 1978


Photo 4. View from northeast showing rear of Carnegie Library and ca. 1934 addition.



Gloria Mills
Kentucky Heritage Commission
Frankfort, Kentucky
March 1978

JUL 7 1978

Photo 5. View from northwest showing high school wing and 1930s addition.



JUL 7 1978

Gloria Mills Kentucky Heritage Commission Frankfort, Kentucky March 1978

Photo 6. Interior of high school wing showing auditorium stage.