



The First Baptist Church
Selma, Alabama, Dallas County


Lawrence Williams c. 1976
Williams Photographic Service,
1116 1st Avenue, Selma, Alabama

Facade, east showing church prior
to tornado damage.

Photo number: 1

JUL 30 1979

SEP 20 1979



Thr First Baptist Church
Selma, Alabama, Dallas County

Lawrence Williams c. 1976
Williams Photographic Services,
1116 1st Avenue, Selma, Alabama

View from southeast, showing
church prior to tornado damage.

Photo number: 2

SEP 20 1979

JUL 30 1979



The First Baptist Church
Selma, Alabama, Dallas County

SELMA-TIMES JOURNAL May, 1978
Selma Times Journal

North wall, showing tornado damage.

Photo number: 3

JUL 30 1979

SEP 20 1979



The First Baptist Church
Selma, Alabama, Dallas County

SELMA TIMES JOURNAL May, 1978
Selma Times Journal

South wall, showing tornado
damage.

Photo number: 4

SEP 20 1979

JUL 30 1979



The First Baptist Church
Selma, Alabama, Dallas County


SELMA TIMES JOURNAL May, 1978
Selma Times Journal

North tower, showing tornado
damage.

Photo number: 5

JUL 30 1979

SEP 20 1979



The First Baptist Church
Selma, Alabama, Dallas County

SELMA TIMES JOURNAL May, 1978
Selma Times Journal

Interior, showing damage.

Photo number: 6

JUL 30 1979

SEP 20 1979



The First Baptist Church
Selma, Alabama, Dallas County

SELMA TIMES JOURNAL May, 1978
Selma Times Journal

Interior, showing damage.

Photo number: 7

JUL 30 1979

SEP 20 1979



The First Baptist Church
Selma, Alabama, Dallas County

Robert Patrick July, 1979
Robert Patrick, 103 Alabama Ave.,
Alabama

Interior

Photo number: 8

JUL 30 1979

SEP 20 1979

*1st Baptist Church - front - looking West
Martin Luther King Sr.*

1979



The First Baptist Church
Selma, Alabama, Dallas County

Robert Patrick July, 1979
Robert Patrick, 103 Alabama Ave.,
Selma

View from south showing restora-
tion underway.

Photo number: 9

SEP 20 1979

JUL 30 1979