



Bogue Chitto, Lincoln County, MS  
Facade (north), view to south  
Photo 1 of 16



Bogue Chitto, Lincoln County, MS  
North + east elevations, view to southwest  
Photo 2 of 16



Boque Chitto, Lincoln County, MS  
East elevation, view to west  
Photo 3 of 16



Bogue Chitto, Lincoln County, MS  
Bay window + gable details, view to south  
Photo 4 of 16





Bogue Chitto, Lincoln County, MS  
Exterior window detail, view to east  
Photo 5 of 16



Bogue Chitto, Lincoln County, MS  
Front porch detail, view to southwest  
Photo 6 of 16



Boque Chitto, Lincoln County, MS  
Cable detailing, view to south  
Photo 7 of 16



Bogue Chitto, Lincoln County, MS  
Entrance & surround, view to south  
Photo 8 of 16





Bogue Chitto, Lincoln County, MS  
Mantlepiece in southeastern room, view to north  
Photo 9 of 16



Bogue Chitto, Lincoln County, MS  
Mantle piece in northeastern room, view to south  
Photo 10 of 16



Bogue Chitto, Lincoln County, MS  
Hall screen, main hallway, view to south  
Photo 11 of 16



Bogue Chitto, Lincoln County, MS  
Corner of baseboard, southeastern room, view to S  
Photo 12 of 16





Bogue Chitto, Lincoln County, MS  
Interior window surround, northeastern room, view  
to north

Photo 13 of 16



Bogue Chitto, Lincoln County, MS

Interior door surround, northeastern room, view to  
east

Photo 14 of 16



Bogue Chitto, Lincoln County, MS  
Interior door surround, bathroom at end of  
entrance hallway, view to south  
Photo 15 of 16



Bogue Chitto, Lincoln County, MS  
Southeastern room, conference room, view to northeast  
Photo 16 of 16