

DAVID JONES HOUSE 720 Tuckaleechee Pk, Maryville, Blount County, Tennessee Photo by: J.L. Driskill

Date: November, 1981 Neg.: Tennessee Historical Comm., Nashville View toward northeast Southwest elevation #1 of 10



DAVID JONES HOUSE 720 Tuckaleechee Pk, Maryville, Blount County, Tennessee Photo by: J.L. Driskill Date: November, 1981 Neg.: Tenn. Hist. Comm., Nashville View toward southeast Northwest elevation, 1957 addition #2 of 10



DAVID JONES HOUSE 720 Tuckaleechee Pk, Maryville Blount County, Tennessee Photo by: J.L. Driskill Date: November, 1981 Neg.: Tenn. Hist. Comm., Nashville View toward southwest Northeast elevation

#3 of 10



DAVID JONES HOUSE 720 Tuckaleechee Pk, Maryville Blount County, Tennessee

Photo by: J. L. Driskill Date: November, 1981 Neg.: Tenn. Hist. Comm., Nashville View toward northwest

Southeast elevation

#4 of 10



DAVID JONES HOUSE 720 Tuckaleechee Pk, Maryville Blount County, Tennessee Photo by: Mary Giacomini

Date: November, 1981

Neg.: Tenn. Hist. Comm., Nashville
View toward northeast
Detail of central pavilion, showing quoins,
 ballustrade, patterned roof
#5 of 10



DAVID JONES HOUSE
720 Tuckaleechee Pk, Maryville
Blount County, Tennessee
Photo by: Gary Coulter
Date: November, 1981

Neg.: Tenn. Hist. Comm., Nashville Interior view Foyer, showing woodwork in arch, stair #6 of 10



DAVID JONES HOUSE 720 Tuckaleechee Pk, Maryville Blount County, Tennessee Photo by: Gary Coulter

Neg.: Tenn. Hist. Comm., Nashville Interior view

Date: November, 1981

Detail of large windows in bay of living room; oak woodwork, molding, high ceiling #7 of 10



DAVID JONES HOUSE 720 Tuckaleechee Pk. Marvy

720 Tuckaleechee Pk, Maryville Blount County, Tennessee

Photo by: Gary Coulter Date: November, 1981

Neg.: Tenn. Hist. Comm., Nashville

Interior view

Ornate fireplace with carved oak mantel & framed mirror in dining room #8 of 10



DAVID JONES HOUSE 720 Tuckaleechee Pk, Maryville

Photo by: Gary Coulter
Date: November, 1981

Neg.: Tenn. Hist. Comm., Nashville Interior view Fireplace with decorative tile & carved oak mantel in living room

#9 of 10



DAVID JONES HOUSE 720 Tuckaleechee Pk, Maryville Blount County, Tennessee Photo by: 'Gary Coulter Date: November, 1981 Neg.: Tenn. Hist. Comm., Nashville

Interior view
Fireplace with black marble and carved oak mantel in living room
#10 of 10