Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
Northeast view

1/18

OCT 31 1980

FEB 20 1980

Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
South facade

OCT 31 1980

2/18

FEB 20 1980

Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
South facade

OCT 31 1980

3/18

FEB 20 1980

Hilton OCT 31 1980 FEB 20 1980
Baltimore County, Maryland
Mike Schumann 11/22/77 4/18
Neg. with M. Schumann
Black and white Italian Marble in Checkerboard fashion center hallway; looking from large west room (called the Living Room) toward the Dining Room

Black and white Italian marble in checkerboard fashion center hallway; looking from large west room (called the Living Room in the original drawings) toward the Dining Room.

Hilton
Baltimore County, Maryland
Mike Schumann 11/22/77
Neg. with M. Schumann
Stairway and banister from 1st to 2nd floors in Hilton.

OCT 31 1980 5/18 FEB 20 1980

OCT 3 1 1980

FEB 2 0 1980

Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
Door leading to terrace of the south facade overlooking broad view of Patapsco River Valley.

6/18

Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg with M. Schumann'
Mahogany Dining Room.

FEB 20 1980

7/8

OCT 31 1980

Hilton

FEB 2 0 1980

Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
One of the fireplaces on the ground floor level

OCT 3 1 1980

8/8

Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
Landing and window before you ascend to top floor of Hilton

FEB 2 0 1980

OCT 3 1 1980

9/18

A-104

OCT 31 1980

FEB 20 1980

Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
Black and White Italian marble floors and black marble baseboards on ground floor and 1st floor level of Hilton.

10/1 P

OCT 31 1980

FEB 20 1980

Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
Examples of the quarter-sawn white oak floors laid in a herringbone pattern throughout the Mansion.

11/18

EXIT

Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
Stairway looking from 2nd floor up to 3rd floor.

FEB 20 1980

OCT 31 1980

12/18

13/18

Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
Double sliding doors open from two easterly rooms to the side hall which passes between them.

FEB 20 1980

OCT 31 1980



Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
Leaded glass window on ground floor to each side of main door to Hilton.

FEB 20 1980

17/18

OCT 31 1980

Hilton
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
Crown moldings in every major room of first three floors.

FEB 20 1980

15/18

OCT 31 1980

HILTON
Baltimore County, Maryland
Mike Schumann, 11/22/77
Neg. with M. Schumann
Two identical fireplaces of the large west room.

FEB 20 1980

16/18

OCT 31 1980

Hilton
Baltimore County, Maryland
Mike Schumann 11/22/77
Neg. with M. Schumann
Northwest view-Main Entrance

12/18

OCT 31 1980 FEB 20 1980

Hilton
Baltimore County, Maryland
Mike Schumann 11/22/77
Neg. with M. Schumann
South facade overlooks broad view of the
Patapsco River Valley.

18/18

OCT 31 1980 FEB 20 1980

Hilton Mansion, Baltimore County
Photographer, Mike Schumann
11/22/77
South facade overlooks broad view of
Patapsco River valley.