

SECURITY STATE BANK

SECURITY
STATE
BANK

GREENHOUSE
CO.



Security State Bank Building (netHS# C105-66)
Broken Bow, Custer County, Nebraska.

HP 2

PHOTOGRAPH BY D. MURPHY
NEBR. STATE HISTORICAL SOCIETY
JULY, 1976 (NSHS 7607/32:26)

VIEW LOOKING SOUTHWEST SHOWING
THE NORTH AND EAST FACADES.

PHOTO # 1 OF 5

SECURITY STATE BANK

SECURITY
STATE
BANK



HP # 1

SECURITY STATE BANK BUILDING (NEHBS # CND5-66)
BROKEN BOW, CUSTER COUNTY, NEBRASKA

PHOTOGRAPHER UNKNOWN

NEBR. STATE HISTORICAL SOCIETY COLLECTIONS
CA. 1979 (NSHS # 673.5-4589)

HISTORIC PHOTO FROM OLD CALENDAR
VIEW LOOKING SOUTHWEST SHOWING
NORTH AND EAST FACADES.

PHOTO # 2 OF 5



HP 2

SECURITY STATE BANK BUILDING (NEHBS # C405-66)
BROKEN BOW, CUSTER COUNTY, NEBRASKA

PHOTOGRAPH BY LARRY HICKENBOTTOM,
LARRY'S PHOTO, BROKEN BOW, NEBRASKA
FOR NEBRASKA STATE HISTORICAL SOCIETY
JULY, 1987 (NSHS 8707/1:3)

INTERIOR VIEW LOOKING WEST
NORTHWEST TOWARD REAR EXIT.

PHOTO # 3 OF 5



HP #2

SECURITY STATE BANK BUILDING (NetBS#CU05-66)
Broken Bow, Custer County, NEBRASKA

PHOTOGRAPH BY F.E. TAYLOR, TAYLOR'S STUDIO, Broken Bow, Ne.
NEBRASKA STATE HISTORICAL SOCIETY COLLECTIONS
1915 (NSHS #1673.5-4591)

HISTORIC VIEW OF BANK INTERIOR
LOOKING WEST.

PHOTO #4 OF 5



HP2

SECURITY STATE BANK BUILDING (NEHBS #C105-66)
BROKEN BOW, CUSTER COUNTY, NEBRASKA

PHOTOGRAPH BY LARRY HICKENBOTTOM,
LARRY'S PHOTO, BROKEN BOW, NE. FOR
NEBRASKA STATE HISTORICAL SOCIETY
JULY, 1987 (NSHS 8707/1:16)

INTERIOR VIEW LOOKING EAST
NORTHEAST TOWARD FRONT ENTRY.

PHOTO # 5 OF 5