



1000
1000

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Glyndon		SEP 20 1973
2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon
STREET AND NUMBER		
north and south sides of Butler Road; east and west sides of Chatsworth Avenue		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Anthony O. James	July 1973	Maryland Historic Trust 2525 Riva Road Annapolis, Maryland 21401
4. IDENTIFICATION		
DESCRIBE VIEW, DIRECTION, ETC.		

Southeast
street vista: Chatsworth Avenue
1 of 11 photos





UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

(Type all entries - attach to or enclose with photograph)

1. NAME		NUMERIC CODE <i>(Assigned by NPS)</i>
COMMON	AND/OR HISTORIC	SEP 20 1973
Glyndon		

2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon


STREET AND NUMBER

north and south sides of Butler Road; east and west sides of Catsworth Avenue

3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Anthony O. James	July 1973	Maryland Historic Trust 2525 Riva Road Annapolis, Maryland 21404

4. IDENTIFICATION
DESCRIBE VIEW, DIRECTION, ETC.

Looking south
Waugh Ave in
Emory Grove Camp Ground
#2 of 11 photos





UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Glyndon		SEP 20 1973

2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon
STREET AND NUMBER		

north and south sides of Butler Road; east and west sides of Chatsworth Avenue.

3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Anthony O. James	July 1973	Maryland Historic Trust 2525 Riva Road Annapolis, Maryland 21401

4. IDENTIFICATION
DESCRIBE VIEW, DIRECTION, ETC.

Southeast Fadades
Houses on Chatsworth Avenue
#3 of 11 photos






UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Glyndon		SEP 20 1973
2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon
STREET AND NUMBER		
north and south sides of Butler Road; east and west sides of Chatsworth Avenue		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Anthony O. James	July 1973	Maryland Historic Trust 2525 Riva Road Annapolis, Maryland 21401
4. IDENTIFICATION		
DESCRIBE VIEW, DIRECTION, ETC.		

West Street vista:
Chatsworth Avenue
#4 of 11 photos





UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Glyndon		SEP 20 1973
2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon
STREET AND NUMBER		
north and south sides of Butler Road; east and west sides of Chatsworth Avenue		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Anthony O. James	July 1973	Maryland Historic Trust 2525 Riva Road Annapolis, Maryland 21401
4. IDENTIFICATION		

DESCRIBE VIEW, DIRECTION, ETC.

East Facades Temperance Park

5 of 11 photos





**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE <i>(Assigned by NPS)</i>
Glyndon		SEP 20 1973
2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon
STREET AND NUMBER		
north and south sides of Butler Road; east and west sides of Chatsworth Avenue		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Anthony O. James	July 1973	Maryland Historic Trust 2525 Riva Road Annapolis, Maryland 21401
4. IDENTIFICATION		
DESCRIBE VIEW, DIRECTION, ETC.		

East Facade: Tabernacle
Emory Grove Camp Ground
#6 of 11 photos





UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Glyndon		SEP 20 1973

2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon
STREET AND NUMBER		


north and south sides of Butler Road; east and west sides of Chatsworth Avenue

3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Anthony O. James	July 1973	Maryland Historic Trust 2525 Riva Road

4. IDENTIFICATION		
DESCRIBE VIEW, DIRECTION, ETC.		

Interior; looking northwest
Tabernacle
Emory Grove Campground

7 of 11 photos





NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Glyndon		SEP 20 1973
2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon
STREET AND NUMBER		
north and south sides of Butler Road; east and west sides of Chatsworth Avenue		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Rodd L. Wheaton	1972	Maryland Historical Trust 2525 Riva Road Annapolis, Maryland 21401
4. IDENTIFICATION		

DESCRIBE VIEW, DIRECTION, ETC.

Burgess House - South elevation

#8 of 11 photos





UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Glyndon		SEP 20 1973
2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon
STREET AND NUMBER		
north and south sides of Butler Road; east and west sides of Chatsworth Avenue		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Rodd L. Wheaton	1972	Maryland Historical Trust 2525 Riva Road Annapolis, Maryland

4. IDENTIFICATION
DESCRIBE VIEW, DIRECTION, ETC.
Emory Grove Hotel - Southeast elevation #9 of 11 photos





UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Glyndon		SEP 20 1973
2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon
STREET AND NUMBER		
north and south sides of Butler Road; east and west sides of Chatsworth Avenue		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Rodd L. Wheaton	1972	Maryland Historical Trust 2525 Riva Road Annapolis, Maryland 21401


4. IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC.

Broadbent House - South elevation

10 of 11 photos





UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Glyndon		SEP 20 1973

2. LOCATION		
STATE	COUNTY	TOWN
Maryland	Baltimore	Glyndon
STREET AND NUMBER		

north and south sides of Butler Road; east and west sides of Chatsworth Avenue

3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Rodd L. Wheaton	1972	Maryland Historical Trust 2525 Riva Road Annapolis, Maryland 21401

4. IDENTIFICATION
DESCRIBE VIEW, DIRECTION, ETC.

Glyndon Women's club - north elevation

11 of 11 photos

