



Name Lexington Dry Goods Company Building Location 249-51 E. Main St., Lexington, KY. Photographer Bettie L. rKerr Date Taken_ July, 1985 Negative Location The Historic Commission View Lexington Dry Goods Building looking northeast Photo # 1





Photo # 2

Name Lexington Dry Goods Company Building
Location 249-51 E. Main St., lexington, KY.
Photographer Bettie L. Kerr
Date TakenJuly, 1985
Negative Location The Historic Commission
View northeast view of top floor and cornice





Name	Lex	ington	Dry Good	ds Cor	mpany Building
-					Lexington, KY.
			ettie L.		
			ıly, 198		
					c Commission
					orthwest
11011					

Photo # 3





Name Lexington Dry Goods Company Building
Location 249-51 E. Main St., Lexington, KY.
Photographer Bettie L. Kerr
Date TakenJuly, 1985
Negative Location The Historic Commission
View_transom of first floor windows and
guilloche ornamentation between first and
second floors looking northeast





TRANSPORT FOOD
Name Lexington Dry Goods Company Building
Location 249-51 E. Main St., Lexington, KY.
Photographer Bettie L. Kerr
Date TakenJuly, 1985
Negative Location The Historic Commission
View_ rear of building looking south
Photo # 5





Name Lexington Dry Goods Company Building
Location 249-51 E. Main St., lexington, KY.
Photographer Bettie L. Kerr
Date TakenJuly, 1985
Negative Location The Historic Commission
View rear of building showing deteriorating
Loading dock looking southwest
Photo # 6





Name Lexington Dry Goods Company Building Location 249-51 E. Main St., Lexington, KY. Photographer Scott Guyon Date Taken August, 1985 Negative Location Omni Architects View Pressed tin ceiling on first floor

Photo # 7





Name Lexington Dry Goods Company Building
Location 249-51 E. Main St., Lexington, KY.
Photographer Scott Guyon
Date TakenAugust, 1985
Negative Location Omni Architects
View_ looking toward rear of building showing
two metal columns on first floor
Photo # 8





Name Lexington Dry Goods Company Building
Location 249-51 E. Main St., Lexington, KY.
Photographer Scott Guyon
Date TakenAugust, 1985
Negative Location Omni Architects
View round radiators at base of each column
on first floor
Photo # 9






Name Lexington Dry Goods Company Building
Location 249-51 E. Main St., Lexington, KY.
Photographer Scott Guyon
Date Taken August, 1985
Negative Location Omni Architects
View side view of staircase from first to
second floor
Photo # 10





Name Lexington Dry Goods Company Building
Location 249-51 E. Main St., Lexington, KY.
Photographer Scott Guyon
Date Taken August, 1985
Negative LocationOmni Architects
View_front view of staircase from first to
second floor
Photo # 11





Name Lexington Dry Goods Company Building
Location 249-51 E. Main St., Lexington, KY.
Photographer Scott Guyon
Date TakenAugust, 1985
Negative LocationOmni Architects
View_ passenger elevator which runs from
basement to fourth floor
Photo # 12