





HUNTERDON ART CENTER

7 CENTER STREET, CLINTON, N. J. 08809

Hunterdon Art Center

Clinton, Hunterdon County, New Jersey

view of the mill and dam looking north east

negative: Milford, New Jersey

photography: Mark Walker

Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
View of the mill and dam,
looking northeast
Photo by Mark Walker
Milford, NJ 1980



ART
CENTER

2



HUNTERDON ART CENTER

7 CENTER STREET, CLINTON, N. J. 08809

Hunterdon Art Center

Clinton, Hunterdon County, New Jersey

view of the Hunterdon Art Center,
looking north

negative: Milford, New Jersey

photography: Mark Walker

Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
View of the main grist mill
and plaster mill extension,
looking north

Photo by Mark Walker
Milford, NJ 1980

2





HUNTERDON ART CENTER

7 CENTER STREET, CLINTON, N. J. 08809

Hunterdon Art Center

Clinton, Hunterdon County, New Jersey

view of the Hunterdon Art Center from
west side, across river

negative: Milford, New Jersey

photography: Mark Walker

Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
Hill from river. Note
raceway arch just above
ground level. View looking
east.

Photo by Mark Walker
Milford, NJ 1980



Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
Hoisting canopy and Gibbs
surround with datestone.
View looking west.

Photo by Mark Walker
Milford, NJ 1980



HUNTERDON ART CENTER

7 CENTER STREET, CLINTON, N. J. 08809

Hunterdon Art Center

Clinton, Hunterdon County, New Jersey

view of keystone and gambrel roof
from street

negative: Milford, New Jersey

photography: Mark Walker



Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
Interior, first floor,
showing massive framing and
grain chute.

Photo by Mark Walker
Milford, NJ 1980



HUNTERDON ART CENTER
7 CENTER STREET, CLINTON, N. J. 08809


Hunterdon Art Center

Clinton, Hunterdon County, New Jersey

view of first floor showing front door,
chamfered post and milling mechanism

negative: Milford, New Jersey

photography: Mark Walker



6.



HUNTERDON ART CENTER

7 CENTER STREET, CLINTON, N. J. 08809

Hunterdon Art Center

Clinton, Hunterdon County, New Jersey

view of milling mechanism on first floor

negative: Milford, New Jersey

photography: Mark Walker

Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
Grain shute on first floor
Photo by Mark Walker
Milford, NJ 1980





HUNTERDON ART CENTER

7 CENTER STREET, CLINTON, N. J. 08809

Hunterdon Art Center

Clinton, Hunterdon County, New Jersey

view of mill stone on second floor

negative: Milford, New Jersey

photography: Mark Walker

Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
Mill stone in mill
Photo by Mark Walker
Milford, NJ 1980

7





HUNTERDON ART CENTER

7 CENTER STREET, CLINTON, N. J. 08809

Hunterdon Art Center

Clinton, Hunterdon County, New Jersey

chamfered post and supports on third floor

negative: Milford, New Jersey

photography: Mark Walker


Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
Framing supports on third
floor.
Photo by Mark Walker
Milford. NJ 1980



Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
The mill in 1953. Joseph
Kreidel, miller.
Shepherd Photo, 124 Main St.,
Flemington, NJ



Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
The mill in 1953. Main floor.
Shepherd Photo, 124 Main St.,
Flemington, NJ




Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
Third Floor. 1953
Shepherd Photo, 124 Main St.,
Flemington, NJ

12



Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
The mill in 1953. Main floor.
Shepherd Photo, 124 Main St.,
Flemington, NJ



Dunham's Mill/Parry's Mill
Clinton, Hunterdon County, NJ
Third floor. 1953
Shepherd Photo, 124 Main St.,
Flemington, NJ

13