



1. Sanseer Mill
Middletown, CT

View: Mill A in foreground; Mill
B left rear

Negative on file Conn. Hist. Comm.
Facing: SW

Cunningham

5/85



2. Sanseer Mill
Middletown, CT

View: Mill A - south and east elevations

Facing: W

Negative on file Conn. Hist. Commission
Cunningham 5/85



3. Sanseer Mill
Middletown, CT

View: Mill A - ~~W~~ elevation

Facing: NE

Negative on file Conn. Hist. Commission

Cunningham

9/85



4. Sanseer Mill
Middletown, CT

View: Mill A.- south elevation

Facing: NW

Negative on file Conn. Hist. Commission
Cunningham 5/85



5. Sanseer Mill
Middletown, CT

View: Mill A.-Northwest elevation

Facing: S

Negative on file Conn. Hist. Commission
Cunningham 5/85

A black and white photograph of a building's entrance. The entrance is framed by a portico supported by four white columns. The name "P&H. BLISS" is inscribed on the pediment above the columns. The building is made of dark brick. There are windows above the entrance and a door with a transom window. A large bush is in the foreground.

P&H. BLISS

6. Sanseer Mill
Middletown, CT

View: Portico on NW elevation
Negative on file Conn. Hist. Commission
Facing: SE

Cunningham

5/85



7. Sanseer Mill
Middletown, CT

View: Mill B - SW and SE elevations

Facing: N
Negative on file Conn. Hist. Commission

Cunningham

9/85



8. Sanseer Mill
Middletown, CT

View: Mill B - South elevation

Facing: NW

Negative on file Conn. Hist. Commission

Cunningham

5/85



9. Sanseer Mill
Middletown, CT

View: Southwest elevation Mill C
Detail: Arched opening in
foundation and clapboards.

Facing: NE

Negative on file Conn. Hist. Commission
Cunningham 1/86



10. Sanseer Mill
Middletown, Ct

View: Mill C - NW and SW elevations.
Note remains of foundation
in foreground.

Facing: SE

Negative on file Conn. Hist. Commission
Cunningham 1/86



11. Sanseer Mill
Middletown, CT

View: Interior Mill A - first floor

Facing: N

Negative on file Conn. Hist. Commission

Cunningham

5/85



12. Sanseer Mill
Middletown, CT

View: Interior of Mill A stair tower
Elevator shaft in center (2nd floor)

Facing: E

Negative on file Conn. Hist. Commission
Cunningham

5/85



13. Sanseer Mill
Middletown, CT

View: Interior of Mill B - attic.

Facing: W

Negative on file Conn. Hist. Commission

Cunningham

5/85



14. Sanseer Mill
Middletown, CT

View: Interior Mill C - main floor

Facing: S

Negative on file Conn. Hist. Commission

Cunningham

10/85



15. Sanseer Mill
Middletown, CT

View: Interior Mill - 2nd floor rear wall

Facing: SE

Negative on file Conn. Hist. Commission
Cunningham

5/85



16. Sanseer Mill
Middletown, CT

View: Interior Mill C - staircase from
attic to 2nd floor. Note one-piece
balustrade.

Facing: W

Negative on file Conn. Hist. Commission
Cunningham

5/85




17. Sanseer Mill
Middletown, CT

View: Interior Mill C - 2nd floor

Facing: N
Negative on file Conn. Hist. Commission
Cunningham

5/85



18. Sanseer Mill
Middletown, CT

View: Interior Mill C. - 1st floor ceiling

Facing: S

Negative on file Conn. Hist. Commission

Cunningham

10/85