





CAT

215

RUL RUPSONY

KTA OPA

13-10

W3W



KTA-04-01 DEPT 3 DETAIL BENG =

13-10

ZCS  
08

RET NOL DEMO

NOV 8



KTA. PFA. RA. DOCKO DEFF 3 DET NOL DEMO.



ZCR  
C8



2 LARGE  
1-Topping  
Pizzas for  
\$13.99

PIZZA  
**PAPA JOHN'S**





PRINCE





PENNY

R120K-SWOL-2/11/03

R

13-10

2 Lanes  
1-1/2 Miles  
PA 10R  
\$13.99

PA 10R







United States Department of the Interior  
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES  
CONTINUATION SHEET

Section Photographs Page 19

**Clark Avenue Railroad Underpass, Las Vegas, Clark County, Nevada**

---

**Index to Attached Photographs**

B & W

ASA 125

Taken: September 2003

Negatives located at: Nevada State Museum and Historical Society

Photographer: Courtney Mooney

<b>Photograph #</b>	<b>Direction Facing</b>	<b>View Description</b>
#1	West	East elevation showing original north abutment and addition of span and center and south abutments constructed 1964.
#2	West	East elevation showing walkway to pedestrian subway—now closed. Original handrails in background.
#3	West	East elevation showing now closed entrance to pedestrian subway with original handrails.
#4	Southwest	Right side of east elevation showing fascia, abutments, and handrail.
#5	Southwest	East elevation showing relation of fascia to abutments.
#6	West	East elevation showing original abutment constructed 1936.

United States Department of the Interior  
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES  
CONTINUATION SHEET

Section Photographs Page 20

**Clark Avenue Railroad Underpass, Las Vegas, Clark County, Nevada**

---

---

**Index to Attached Photographs, Continued**

<b>Photograph #</b>	<b>Direction Facing</b>	<b>View Description</b>
#7	East	West elevation showing closed pedestrian walkway on left and addition of span and center and south abutments constructed 1964.
#8	East	West elevation showing addition of span and center and south abutments constructed 1964.
#9	East	West elevation showing close-up of center abutment constructed 1964.
#10	North	Rear of west elevation showing tops of abutments with relation to fascia. Also showing top surface of underpass.
#11	East	Rear of east elevation showing top surfaces of underpass including railroad tracks and railing.
#12	N/A	Bottom of underpass showing steel structure.