



Photo Number 1 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Southern (main) Facade

Negative: On File at Historic Landmarks
Foundation of Indiana



Photo Number: 2 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Main Entrance

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number: 3 of 29

Van Nuys Farmhouse

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Iron hitching ring on sidewalk
between driveway and west facade
of house

Negative: On file at Historic Landmarks
Foundation of Indiana



Photo Number: 4 of 29

Van Nuys Farmhouse

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Western Facade Looking North-East

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number: 5 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Western facade looking south-east

Negative: On File at Historic Landmarks
Foundation of Indiana



Photo Number: 6 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Northern Facade

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number: 7 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Eastern Facade Looking South-West

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number: 8 of 29

Van Nuys Farmhouse

Date of Photo: Winter, 1866

Photographer: Suzanne T. Rollins

View: Eastern Facade Looking North-West

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number: 9 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Main Stairway, Front Hall

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number: 10 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Wood Trim on Door Between Living Room
and Dining Room

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number: 11 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Medallion with leather inlay, front
parlor

Negative: On File at Historic Landmarks
Foundation of Indiana



Photo Number 12 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Fireplace

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number: 13 of 29

Van Nuys Farm--Barn and Corn Crib, c. 1840

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Facing North-West

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number 14 of 29

Van Nuys Farmhouse,

Hopewell, Indiana

Date of Photograph: Winter, 1986

View: Interior of Corn Crib

Photographer: Suzanne T. Rollins

Negative: On File at Historic Landmarks
Foundation of Indiana




Photo Number:

15 of 29

Van Nuys Farm--Buggy Shed, c. 1840

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Looking North-East

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number:

16 of 29

Van Nuys Farm--Barn, c. 1940

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Looking North

Negative On File At: Historic Landmarks

Foundation of Indiana



Photo Number 17 of 29

Van Nuys Farmhouse

Hopewell, Indiana

Date of Photograph: Summer, 1986

Photographer: Suzanne T. Rollins

View: Main Barn Looking Southeast

Negative: On File At Historic Landmarks
Foundation of Indiana




Photo Number 18 of 29

Van Nuys Farmhouse

Hopewell, Indiana

Date of Photograph: Summer, 1986

Photographer: Suzanne T. Rollins

View: Interior of Main Barn

Negative: On File at Historic Landmarks
Foundation of Indiana




Photo Number: 19 of 29

Van Nuys Farm--Chicken House, c.1885

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Looking North-East

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number: 20 of 29

Van Nuys Farm—Garage, c.1900

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Looking North-West

Negative: On File At Historic Landmarks
Foundation of Indiana




Photo Number 21 of 29

Van Nuys Farmhouse

Hopewell, Indiana

Date of Photograph: Summer, 1986

Photographer: Suzanne T. Rollins

View: Garage (former wheat granary) looking
southeast

Negative: On File at Historic Landmarks
Foundation of Indiana



Photo Number: 22 of 29

Van Nuys Farm--Hog Houses, c.1920

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Looking North-West

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number 23 of 29

Van Nuys Farmhouse

Hopewell, Indiana

Date of Photograph: Summer, 1986

Photographer: Suzanne T. Rollins

View: Hog House Looking northeast

Negative: On File at Historic Landmarks
Foundation of Indiana



Photo Number 24 of 29

Van Nuys Farmhouse

Hopewell, Indiana

Date of Photograph: Summer, 1986

Photographer: Suzanne T. Rollins

View: Hog Shed Showing Foundation of
Former Dairy Barn

Negative: On File at Historic Landmarks
Foundation of Indiana




Photo Number 25 of 29

Van Nuys Farmhouse

Hopewell, Indiana

Date of Photograph: Summer, 1986

Photographer: Suzanne T. Rollins

View: Hog Shed Looking northwest

Negative: On File at Historic Landmarks
Foundation of Indiana



Photo Number 26 of 29

Van Nuys' Farmhouse

Hopewell, Indiana

Date of Photograph: Summer, 1986

Photographer: Suzanne T. Rollins

View: Outbuildings Looking north

Negative: On File at Historic Landmarks
Foundation of Indiana



Photo Number: 27 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Typical full length window seen
in second floor bedroom

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number: 28 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Kitchen Located Within Clapboard

Addition

Negative: On File At Historic Landmarks
Foundation of Indiana



Photo Number 29 of 29

Van Nuys Farmhouse, 1866

Date of Photo: Winter, 1986

Photographer: Suzanne T. Rollins

View: Main Entrance

Negative: On File at Historic Landmarks
Foundation of Indiana