INTENSIVE S	URVEY FORM His	toric Preserva	ation D	ivi	B sion SEE	e H2stori	cal soc	3 OC Nety of	Wiscon	sin
City, Village or Town: City of Milwaukee Milwauke			₽		Surveyor: Virginia A. Palmer			Date: May 27,1985		7
Street Address:					USGS Quad and UTM Reference: Acreage:					Street I. Fredea
34 49-51 N. Frederick Avenue, originally noted as 1013-15 Frederick.				16/428040/4269880 less than 1					an l	rick
Current Name & Use: private residence					Current Owner:					
Film Roll No.					Mr and Mrs. Fred C. Gee Current Owner's Address:					
				3551 N. Frederick Avenue						Avenue
Negative No.				Legal Description:						ωz
Affix Contact Prints Facade Orient.				Lot 9, Block 2 in Mariner's Realty Company Subdivision of a part of the S.W. ½ of S 10, T 7 N, R 22 E, in the City of Milwaukee.						Number 3549-51
Original Na			Source	Pro	evious Owners	Dates	Uses		Source	71
2 Alfred M. Hoelz home										Town 7 N
Dates of Construction /Alteration			Source			· · · · · · · · · · · · · · · · · · ·				
1925		<u> </u>	A							22 R
Architect and/or Builder:			Source							Range 22 E
	. Meyer & Compamy	,Inc.								
3 Architectural Significance ORepresents work of a master OPossesses high artistic values Represents a type, period, or method of construction OEngineering ONone				4 Historical Significance O Assoc. with lives of significant persons O Assoc. with significant historical events O Assoc. with development of a locality O Other: Q None Period of significance:						Section 10
Architectural Description and Significance: The exterior of this 1½ story house is Tennessee quartzite in shades of mauve, russet, pink. It is a two family house with the two halves connected h a five foot link which contains in each half the stairs to the second floor. There is a gable composition roof at the back and hip roof at the forming a bay for each half. The layout is regular. The house is 47 feet long. There are seve airs of ridge dormers, ten gable dormers, and two chimneys with distinctive round openings.				y front n						Map Name Milwaukee Quad.
The interiors of the two haives are mirror images of each other. There is a beam and girder ceiling Interior visited? O Yes O No (over)										
5 Sources of Information (Reference to Above)				6 Representation in Previous Surveys						
A Building Inspector, Milw. City Hall					O HABS O LDMK O WIHP O NRHP					
B				7 Condition Qexcellent Ogood Ofair Opoor Oruins						
				8	District:			- 1001 C	LULUS	ма 7.
<u>C</u>				Opivotal Ocontributing Onon-contributing						Map Code 7.5 minute
D				9	9 Opinion of National Register Eligibility					
Ε					date:initials: Oeligible Onot eligible Ounknown					
F				H	Dnational O					

throughout the downstairs. There is a stone fireplaceand laundry room on the first floor. Casement windows open inward, but the tile has been removed from the cemant sills. A cement stair leads to the second floor. The bathroom floor is one step up from the hallway

There is storage space under the roof. There is a partial basement and the weight of the cement floor in the dining room of the norbhh half caused it to sag, so a huge post was installed to support the floor. Otherwise, the house is in excellent condition. The separate garage is not architecturally significant and therefore not part of this nomination. The house faces east and is located in a neighborhood of both one and two family homes.

This house is architecturally significant because it is one of a gropp of houses built by Arnold F. Meyer according to Ernest Flagg's systemof construction. It is also significant because it is one of two two-family homes in this group.





et or stange is not the at & the shift wat to the state of the state o

ala da la

83





Interior living room



View from northeast